EMERY COUNTY LAND SURVEY MONUMENT RECORD

| Date of field work: | 4-29-97 | | County | Reference | No | 0818300500 |
|---|---------------|------------------------------|--------|------------------|----|------------|
| Type of Monument: | X | Section Corner Bench Mark | | Quarter Other | | r |
| Your Description and Observation of Monument Found (Be Specific): | | | | | | |
| Found Standard BLM | Cap with a mo | und of stone to the | e west | | | |


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, west, southwest, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818300500 NW COR S 14 T18S R8E SLM STD. BLM CAP



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen


Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 14
Township: 18 S.

Range: 8 E.



graig E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD

| Date of field work: | 4-29-97 | | County | Reference | No. | 0818300440 |
|---|---------------|------------------------------|-------------|------------------|--------|------------|
| Type of Monument: | | Section Corner Bench Mark | X | Quarter Other | Corner | - |
| Your Description and Observation of Monument Found (Be Specific): | | | | | | |
| Found Standard BLM | Cap on top of | a hill with a mound . | of stone to | the west | | |

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, west, southwest, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818300440 WEST QTR S 14 T18S R8E SLM STD. BLM CAP SET #5 REBAR S 84'47'36" W , 9.80

SET #5 REBAR N 06'24'51" W , 7.58 S 26'26'20" E , 13.33 SET #5 REBAR

Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen


Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 14
Township: 18 S.

Range: 8 E.



Craig E./Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

DE OF UT

EMERY COUNTY LAND SURVEY MONUMENT RECORD

County Reference No. 0818260500 Date of field work: 4-29-97 Quarter Corner Section Corner Type of Monument: Other west 1/16 Bench Mark Your Description and Observation of Monument Found (Be Specific):

Found Standard BLM Cap with a mound of stone to the north

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, west, southwest, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818260500 WEST 1/16 S14 T18S R8E SLM STD. BLM CAP

SET #5 REBAR SET #5 REBAR N 85'02'00" W , 13.30 SET #5 REBAR S 09'35'17' S 42'09'33" W , 18.86

N 14'30'01" E , 14.44

No. 146602

CRAIG E

Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craia E. Johansen


(435)381-2523 90 South 100 East, Castle Dale, Utah 84513 Phone: Address:

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

14 Section: 18 S. Township:

8 E. Range:



401 A

| EMERY COUNT | Y LAND SURVEY MO | JNUMENI | RECORI | U |
|--|----------------------------------|----------------|--|------------------------------|
| Date of field work: 4-25-97 | _ | County | Reference | No. <u>0818240500</u> |
| Type of Monument: | Section Corner _ Bench Mark _ | Х | | Corner |
| Your Description and Observation o | f Monument Found (Be | e Specific): | | |
| Found Standard BLM Cap with a si | mall mound of stone to | the north | | |
| | · | | | |
| Description of Monument, Reference Location of this Point: | e Monument or Accessor | ries Establish | ed by You | to Perpetuate the |
| Set a #5 rebar north, west, south | vest, and southeast of | Monument | | |
| | | | | |
| Sketch showing Relative Location of Found or Set. Show Supporting and | | | | |
| 1/4 S11 081824050 NORTH QTF T18S R8E STD. BLM | R S14 N 85'02'00" W . SLM | 13.30 R | SET #5 R 14'30'01" E SET #5 REE 09'35'17" E | E , 14.44 Y |
| Certification: | | | | |
| Firm name and/or Surveyor:Joh | ansen & Tuttle Eng. | Craig E. | Johansen | |
| Address: 90 South 100 East, Ca | stle Dale, Utah 84513 | | Phone: | <u>(435) 381–2523</u> |
| This is to certify that I was in respons of my knowledge the information prese | | | in this recor | d and that to the best |
| | <u> </u> | | , () [| 7 |
| Location Diagram: Section: 14 Township: 18 S1 Range: 8 E. | 4 | raig E | Johanser 1998 | No. 146602 Standard CRAIG E. |

E OF U Control of the Contro

| EME | RY COUNTY LAND SURVEY N | ONUMENT RECORD |
|--|---|---|
| Date of field work: | 4-25-97 | County Reference No. 0818220500 |
| Type of Monument: | Section Corner | Quarter Corner |
| | Bench Mark | X Other East 1/16 |
| Your Description and | Observation of Monument Found (| Be Specific): |
| Found Standard BLM (| Cap along a east—west fenceline | |
| | | |
| Description of Monume Location of this Point: | | ories Established by You to Perpetuate the |
| Set a #5 rebar northe | east, northwest, and two #5 rebars | southwest of Monument |
| | | es and Two Reference Points Stating Whether lence where Applicable. Include North Arrow. |
| 5. T18S R8E PON EN STATE | 0818220500 SET #5 REE EAST 1/16 S14 N 85'36'05" W T18S R8E SLM STD. BLM CAP SET #5 REBAR S 64'38'29" W , 32 | , 12.02 SET #5 REBAR O N 74'09'18" E , 7.97 |
| Certification: . | | |
| | rveyor: <u>Johansen & Tuttle Eng.</u> 100 East, Castle Dale, Utah 84513 | Craig E. Johansen Phone: (435) 381–2523 |
| | was in responsible charge of the surveying formation presented herein is true and con | work described in this record and that to the best rect. |
| Location Diagram: Section: 14 Township: 18 S. | 14 | Craig E. Johansen |
| Range: <u>8 E.</u> | 20 | Date (No. 146602) Date (CRAIG E.) |