EMER	RY COUNTY LAN	ID SURVEY N	ONUMENT R	ECORD	
Date of field work:	4-17-97		County Re	eference No	0918700400
Type of Monument:		ction Corner nch Mark		Quarter Co Other	
Your Description and C)bservation of Monu	ument Found (Be Specific):		
Found Standard ECS C	ap in a east, west	, and north fen	ce corner		
Description of Monume Location of this Point:	nt, Reference Monu	ument or Access	ories Established	by You to	o Perpetuate the
Set a #5 rebar north,	west, southwest, c	and southeast o	f Monument		
Sketch showing Relative Found or Set. Show Si	e Location of Monu upporting and/or C	ument Accessorio Contradictory Evid	es and Two Refe dence where App	rence Poin licable. Inc	ts Stating Whether Iude North Arrow.
COUNTY SURPLES OF THE		SET #5 REBA N 88*08'46" W	R a SE	35'30" W , 19 T #5 REBAR	1.13 N
785 SLBM 1981	0918700400 NORTHWEST COR S1 T18S R9E SLM STD. ECS CAP	9 SET #5 REB S 32'28'59" W	AR OS	SET #5 REBA 26°45'03" E ,	
Certification:					
Firm name and/or Sui	rveyor: Johansen	& Tuttle Eng.	Craig E	Johansen	
•	100 East, Castle D		3	Phone:	(435) 381-2523
This is to certify that I of my knowledge the ir	was in responsible cho oformation presented he	arge of the surveyin rein is true and co	g work described in rrect.	this record of	and that to the best
	•	7	Denie P	J. /	/
Location Diagram:			Craig E./	Johansen	SO LAND SUN

Township: 18 S. 9 E. Range:

Section:

19

No. 146602 CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD

EME	ny Courit	THAD SOUAEL W	MOJAOMEIA! UECO!	7 <i>D</i>
Date of field work:	4-17-97		County Reference	e No. <u>0918700340</u>
Type of Monument:		Section Corner		er Corner
		Bench Mark	Other	
Your Description and	Observation of	Monument Found (Be Specific):	
Found a #4 rebar inl	ne with a sout	h, and east fence. (Checked good from tw	o ECS RM Caps
Description of Monum Location of this Point		Monument or Access	sories Established by Y	ou to Perpetuate the
Set a #5 rebar West,	and Southeast	of Monument		
				Points Stating Whether
Found of Set. Show 3	supporting ana/	or contradictory Evid	dence where Applicable	, include North Arrow.
#4 REBAR	0918700340 WEST QTR S 1 T18S R9E SLM #4 REBAR		S 40"36'40" F	_I.
Certification:				
Firm name and/or Su	ırveyor: <u>Johar</u>	nsen & Tuttle Eng.	Craig E. Johans	en
Address: 90 South	100 East, Cas	tle Dale, Utah 84513	Phone	e: <u>(435) 381–2523</u>
_	,	le charge of the surveyin ed herein is true and cor	g work described in this rec rrect.	ord and that to the best
			000	
			raig E. John	insen-
Location Diagram:	į		Craig E/ Johans	en
Section: 19 Township: 18 S.			. 0	1/35P
Range: 9 E.	- 1 5	<i>j</i>		No. 146602 \
			20 Nov. 1998	(CRAIGE)

TE OF UT