

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-11-97 County Reference No. 0818400400
 Type of Monument: X Section Corner _____ Quarter Corner _____
 _____ Bench Mark _____ Other _____


Your Description and Observation of Monument Found (Be Specific):

Found Standard BLM Cap along a east-west fenceline


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar west, southwest, south, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818400400
 NW COR S 22
 T18S R8E SLM
 STD. BLM CAP




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Craig E. Johansen
 Craig E. Johansen

Location Diagram:
 Section: 22
 Township: 18 S.
 Range: 8 E.



20 Nov. 1998
 Date



EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-11-97 County Reference No. 0818400340

Type of Monument: _____ Section Corner X Quarter Corner
 _____ Bench Mark _____ Other _____


Your Description and Observation of Monument Found (Be Specific):

Found Standard ECS Cap with a mound of stone to the west


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, west, southwest, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818400340
 WEST QTR S22
 T18S R8E SLM
 STD. ECS CAP



Certification:


Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.


Location Diagram:

Section: 22
 Township: 18 S.
 Range: 8 E.



Craig E. Johansen
 Craig E. Johansen

20 Nov. 1998
 Date



EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-11-97 County Reference No. 0818340400

Type of Monument: _____ Section Corner X Quarter Corner
 _____ Bench Mark _____ Other _____


Your Description and Observation of Monument Found (Be Specific):

Found Standard BLM Cap along a east-west fence


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar west, southwest, south, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818340400
 NORTH QTR S22
 T18S R8E SLM
 STD. BLM CAP




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
 Section: 22
 Township: 18 S.
 Range: 8 E.



Craig E. Johansen
 Craig E. Johansen

20 Nov. 1998
 Date

