
- TYPE OF MONUMENT: $oxed{f Z}$ SECTION CORNER $oxed{f \Box}$ QUARTER CORNER $oxed{f \Box}$ SIXTEENTH CORNER $oxed{f \Box}$ OTHER
- DESCRIPTION AND DATE OF MONUMENT FOUND:

ON THE DATE OF 11/14/2012 WE FOUND THE MONUMENT FOR THIS CORNER COMMON TO 4 SECTIONS WHICH IS A 1940 2.5" G.L.O. BRASS CAP ON A 2" STEEL PIPE PROTRUDING 1.6' ABOVE THE GROUND. THERE IS A PILE OF STONES CENTERED AROUND THE BASE OF THE MONUMENT MEASURING 4' IN DIAMETER AND PROTRUDING 1' HIGH.

- DESCRIPTION OF MONUMENT SET BY YOU TO PERPETUATE THE LOCATION OF THIS POINT: SET REFERENCE POINTS FOR THE CORNER AS SHOWN.
- SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET, SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:



THE MONUMENT FOR THIS CORNER COMMON TO 4 SECTIONS IS A 1940 2.5" G.L.O. BRASS CAP ON A 2" STEEL PIPE PROTRUDING 1.6' ABOVE THE GROUND. THERE IS A PILE OF STONES CENTERED AROUND THE BASE OF THE MONUMENT MEASURING 4' IN DIAMETER AND PROTRUDING 1' HIGH.

THIS MONUMENT IS FOR:

T16S R9E S15_S14 S22 S23 1940 SLB&M

> SCALE 1"=20" SCALE 1"=20'
> (EXCEPT IN
> TRIVIAL CASES)
> BEARINGS ARE RELATED
> TO WGS 84 WITH
> GPS OBSERVATIONS
> DRAWN BY: AMM
> 11/20/2012
> P.C. M. ANDERSON

CERTIFICATION

COUNTY EMERY

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Not to scale T16S R9E S15 | S14 S22 S23 1940 Stamping on Cap

Date of field Work to Establish, Restore or Rehabilitate Monument: 11/14/2012

11/14/2012 b. Date Monument was used as a Control corner: ___

Robert L. Kay Surveyor's Name (Please Print):_ Firm Name: UELS, LLC Firm Address: 85 SOUTH 200 EAST, VERNAL, UTAH 84078 Phone: 435-789-1017 Utah License Number: 161319 MORATS 19

MORATS 19

MORATS 19

MORATS 19

KANANA

MARKET L.

MARKET L.

KANANA

MARKET L.

MARKET L.

KANANA

MARKET L.


MARKE 1" = 1 Mile 22 = Location of Monument Corner CORNER COMMON TO 4 SECTIONS Name: NORTHEAST CORNER OF SECTION 22 Signature/Date through Seal _T_ 9E R <u>, S.L.</u> B&.M.

_INDEX REF NUMBER <u>17-N</u>

- TYPE OF MONUMENT: ☐ SECTION CORNER ☑ QUARTER CORNER ☐ SIXTEENTH CORNER ☐ OTHER
- DESCRIPTION AND DATE OF MONUMENT FOUND:

ON THE DATE OF 11/14/2012 WE FOUND THE MONUMENT FOR THIS 1/4 CORNER OF MAXIMUM CONTROL WHICH IS A 1940 2.25" G.L.O. BRASS CAP ON A 1" STEEL PIPE PROTRUDING 0.5' ABOVE THE GROUND. THERE IS A PILE OF STONES ON THE WEST SIDE OF THE MONUMENT WHICH MEASURES 4' IN DIAMETER AND PROTRUDING 2' HIGH.

- DESCRIPTION OF MONUMENT SET BY YOU TO PERPETUATE THE LOCATION OF THIS POINT: SET REFERENCE POINTS FOR THE CORNER AS SHOWN.
- SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET, SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:



THE MONUMENT FOR THIS 1/4
CORNER OF MAXIMUM CONTROL IS A
1940 2.25" G.L.O. BRASS CAP ON A
1" STEEL PIPE PROTRUDING 0.5'
ABOVE THE GROUND. THERE IS A PILE
OF STONES ON THE WEST SIDE OF
THE MONUMENT WHICH MEASURES 4' IN DIAMETER AND PROTRUDING 2'

THIS MONUMENT IS FOR:

T16S R9E 1/4 S22 | S23 1940 SLB&M

SCALE 1"=20'
(EXCEPT IN
TRIVIAL CASES)
BEARINGS ARE RELATED
TO WGS 84 WITH
GPS OBSERVATIONS
DRAWN BY: AMM
11/20/2012
P.C. M. ANDERSON

CERTIFICATION

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Not to scale 1/4 S22 | S23 1940


Stamping on Cap

a. Date of field Work to Establish, Restore or Rehabilitate

11/14/2012 Monument: _

b. Date Monument was used as a Control corner: 11/14/2012

Robert L. Kay Surveyor's Name (Please Print):_ Firm Name: UELS, LLC Firm Address: 85 SOUTH 200 EAST, VERNAL, UTAH 84078 Phone: 435-789-1017 Utah License Number: 161319 1" = 1 Mile



= Location of Monument

Corner 1/4 CORNER OF MAXIMUM CONTROL Name: EAST 1/4 CORNER OF SECTION 22


KAYATE OF UT MINING SEC___22_ 16S Т 9E <u>, S.L.</u> B&.M. R

COUNTY EMERY _INDEX REF NUMBER <u>17-L</u>

- TYPE OF MONUMENT: ☐ SECTION CORNER ☑ QUARTER CORNER ☐ SIXTEENTH CORNER ☐ OTHER.
- DESCRIPTION AND DATE OF MONUMENT FOUND:

ON THE DATE OF 11/14/2012 WE FOUND THE MONUMENT FOR THIS 1/4 CORNER OF MAXIMUM CONTROL WHICH IS A 1940 2.25" G.L.O. BRASS CAP ON A 1" STEEL PIPE PROTRUDING 0.8' ABOVE THE GROUND. THERE IS A PILE OF STONES SURROUNDING THE BASE OF THE MONUMENT WHICH MEASURES 4' IN DIAMETER AND PROTRUDING 0.8' HIGH.


- DESCRIPTION OF MONUMENT SET BY YOU TO PERPETUATE THE LOCATION OF THIS POINT: SET REFERENCE POINTS FOR THE CORNER AS SHOWN.
- SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET, SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:



THE MONUMENT FOR THIS 1/4
CORNER OF MAXIMUM CONTROL IS
A 1940 2.25" G.L.O. BRASS CAP
ON A 1" STEEL PIPE PROTRUDING
O.8' ABOVE THE GROUND. THERE IS
A PILE OF STONES SURROUNDING
THE BASE OF THE MONUMENT
WHICH MEASURES 4' IN DIAMETER
AND PROTRUDING 0.8' HIGH.

THIS MONUMENT IS FOR:

T16S R9E 1/4 S15 S22 1940 SLB&M



CERTIFICATION

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Not to scale S22 1940 Stamping on Cap


Date of field Work to Establish, Restore or Rehabilitate

11/14/2012 Monument:

11/14/2012 b. Date Monument was used as a Control corner: _

Robert L. Kay Surveyor's Name (Please Print): Firm Name: UELS, LLC Firm Address: 85 SOUTH 200 EAST, VERNAL, UTAH 84078

Phone: 435-789-1017 Utah License Number:



= Location of Monument

Corner 1/4 CORNER OF MAXIMUM CONTROL Name: NORTH 1/4 CORNER OF SECTION 22


KAY KAY WATER OF UT NOT THE OF

22 _T_ 16S 9E <u>, S.L.</u> B&.M. COUNTY EMERY _INDEX REF NUMBER <u>15-N</u>

- TYPE OF MONUMENT: ☒ SECTION CORNER ☐ QUARTER CORNER ☐ SIXTEENTH CORNER ☐ OTHER
- DESCRIPTION AND DATE OF MONUMENT FOUND:

ON THE DATE OF 11/14/2012 WE FOUND THE MONUMENT FOR THIS CORNER COMMON TO 4 SECTIONS WHICH IS A 1940 2.5" G.L.O. BRASS CAP ON A 2" STEEL PIPE PROTRUDING 2' ABOVE THE GROUND. THERE IS A PILE OF STONES AROUND THE BASE OF THE MONUMENT MEASURING 4' IN DIAMETER AND PROTRUDING 1' HIGH. THERE IS A RED T-POST 2' NORTH OF THE MONUMENT PROTRUDING 5' HIGH.

- DESCRIPTION OF MONUMENT SET BY YOU TO PERPETUATE THE LOCATION OF THIS POINT: SET REFERENCE POINTS FOR THE CORNER AS SHOWN.
- SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET, SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:



THE MONUMENT FOR THIS CORNER COMMON TO 4 SECTIONS IS A 1940 2.5" G.L.O. BRASS CAP ON A 2" STEEL PIPE PROTRUDING 2' ABOVE THE GROUND. THERE IS ALSO A PILE OF STONES AROUND THE BASE OF THE MONUMENT MEASURING 4' IN DIAMETER AND PROTRUDING 1' HIGH. THERE IS A RED T-POST 2' NORTH OF THE MONUMENT PROTRUDING 5' HIGH.

T16S R9E S16_S15 THIS MONUMENT S21 S22 1940

SLB&M

SCALE 1"=20'
(EXCEPT IN
TRIVIAL CASES)
BEARINGS ARE RELATED
TO WGS 84 WITH
GPS OBSERVATIONS
DRAWN BY: AMM
11/19/2012
P.C. M. ANDERSON

CERTIFICATION

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Firm Address: 85 SOUTH 200 EAST, VERNAL, UTAH 84078

Robert L. Kay

Not to scale 165 R9E S16 ₁ S15 S21 | S22 1940 Stamping on Cap

a. Date of field Work to Establish, Restore or Rehabilitate 11/14/2012 Monument:_

b. Date Monument was used as a Control corner: 11/14/2012

1" = 1 Mile = Location of Monument

Surveyor's Name (Please Print):_

Phone: 435-789-1017 Utah License Number:

Firm Name: UELS, LLC

Corner Corner common to 4 sections Name: NORTHWEST CORNER OF SECTION 22

Т

22

No page of the signature/Date the Signature/Date through Seal

9E

R

161319


<u>, S.L.</u> B&.M. COUNTY EMERY _INDEX REF NUMBER <u>13-N</u>

16S

- TYPE OF MONUMENT: ☐ SECTION CORNER ☑ QUARTER CORNER ☐ SIXTEENTH CORNER ☐ OTHER
- DESCRIPTION AND DATE OF MONUMENT FOUND:


ON THE DATE OF 11/14/2012 WE FOUND THE MONUMENT FOR THIS 1/4 CORNER OF MAXIMUM CONTROL WHICH IS A 1940 2.25" G.L.O. BRASS CAP PROTRUDING 1.5' ABOVE THE GROUND. THERE IS A PILE OF STONES SURROUNDING THE BASE OF THE MONUMENT WHICH MEASURES 3' IN DIAMETER AND PROTRUDING 1.5' HIGH.

- DESCRIPTION OF MONUMENT SET BY YOU TO PERPETUATE THE LOCATION OF THIS POINT: SET REFERENCE POINTS FOR THE CORNER AS SHOWN.
- SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET, SHOW SUPPORTING AND/OR CONTRADICTORY EVIDENCE WHERE APPLICABLE:



THIS MONUMENT

T16S R9E 1/4 S21 | S22



CERTIFICATION

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Firm Address: 85 SOUTH 200 EAST, VERNAL, UTAH 84078

Not to scale S21 | S22 1940 Stamping on Cap

Date of field Work to Establish, Restore or Rehabilitate Monument: 11/14/2012

11/14/2012 b. Date Monument was used as a Control corner: _

Phone: 435-789-1017 Utah License Number: 1'' = 1 Mile

Surveyor's Name (Please Print): ___

Firm Name: UELS, LLC

= Location of Monument

Corner 1/4 CORNER OF MAXIMUM CONTROL Name: WEST 1/4 CORNER OF SECTION 22

TATE OF UTANTIN Signature/Date through Seal

161319

Robert L. Kay

22 Τ_ 16S 9E SEC <u>, S.L.</u> B&.M. COUNTY EMERY _INDEX REF NUMBER <u>13-L</u>