EME	RY COUNTY	EMERY COUNTY LAND SURVEY MONUMENT RECORD									
Date of field work:	4-14-97		County	Reference No. <u>0818400240</u>							
Type of Monument:		Section Corner Bench Mark	Х	Quarter Corner Other							
Your Description and	Observation of	Monument Found (Be Specific):								
Found two ECS RM Co	aps										
Description of Monume Location of this Point		Monument or Access	ories Establish	ned by You to Perpetuate the							
Set a P-K Nail for th	ne corner, and	a P—K Nail in the	curb southwes	t, and northwest of Monument							
				eference Points Stating Whethe Applicable. Include North Arrow.							
PK NAIL	0818400240 WEST QTR S27 T18S R8E SLM PK NAIL	SET PK NAIL N 75'06'11" W , 43.39 7 M S 65'26'43" W , 45.38 SET PK NAIL		ECS RM CAP, 37.07 1000 NORTH S 43'52'16" E , 55.06 ECS RM							
Certification:											
Firm name and/or St Address: 90 South		nsen & Tuttle Eng. stle Dale, Utah 8451.		. Johansen Phone: <u>(</u> 435) 381–2523							
		ole charge of the surveyir ted herein is true and co		in this record and that to the best							
Location Diagram:			Ziaig E	Johansen Johansen							

Section: 27
Township: 18 S.
Range: 8 E.

20 Nov. 1998 Date No. 146602 CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-10-97 County Reference No. 0818400300

Type of Monument: X Section Corner Quarter Corner

Bench Mark Other

Your Description and Observation of Monument Found (Be Specific):

Found Standard BLM Cap with a small mound of stone to the north


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, west, southeast, and southwest of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818400300 NW COR S 27 T18S R8E SLM STD. BLM CAP



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 27

Township: 18 S.

Range: 8 E.

----27-----

Craig E. Johansen

.

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD


Date	of field work:	4-10-97		County	Reference	No.	0818340300
Туре	of Monument:		Section Corner Bench Mark	X	Quarter Other	Corn	er
Your	Description and	Observation of	Monument Found (Be Specific):			

Found Standard ECS Cap at a north-south-east fence corner

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set two #5 rebars south, and east of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.




Firm name and/or Surveyor: <u>Johansen & Tuttle Eng.</u> <u>Craig E. Johansen</u>

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
Section: 27
Township: 18 S.
Range: 8 E.



Craig E Johansen Craig E Johansen No. 146692

20 Nov. 1998
Date