## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:

4-16-97

County Reference No. 0818600300

Type of Monument:

Χ

Section Corner Bench Mark

Quarter Corner

Other


Your Description and Observation of Monument Found (Be Specific):

Found Standard ECS Cap along a north-south fence

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, and three northeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



SET #5 REBAR SET #5 REBAR N 38'26'46" E , 24.59 N 65'28'31" E 32.89 N 00'29'54" W , 10.94 SET #5 REBAR

NORTHWEST COR S29 T18S R8E SLM STD. ECS CAP

0818600300

Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng.

Craig E. Johansen

Address:

90 South 100 East, Castle Dale, Utah 84513

Phone:

Johansen

(435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section:

Township:

18 S.

Range:

8 E.

No. 146602 CRAIG F. JOHANSEN

## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:

4-16-97

County Reference No. 0818540300

Type of Monument:

Section Corner

Bench Mark

Quarter Corner

Other


Your Description and Observation of Monument Found (Be Specific):

Found Standard ECS Cap along a north-south fence


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Located existing prorerty corner monuments to the north, south, northwest, and southwest of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



08540300 NORTH QTR S 29 T18S R8E SLM STD. ECS CAP



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng.

Craia E. Johansen

Address:

90 South 100 East, Castle Dale, Utah 84513

Phone:

(435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section:

29

Township:

18 S.

Range:

8 E.

No. 146602 <del>CRAIG</del> E. JOHANSEN

TE OF U

## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	4-14-97			County Re	eference	No. <u>0818600240</u>
Type of Monument:		Section Corne	er	X	Quarter	Corner
	errorial designation of the control	Berich Mark		·	Other -	
Your Description and	Observation of	Monument Four	nd ( Be S <sub>l</sub>	pecific ):		
Found Standard ECS	RM Cap behind	sidewalk along	north side	e of center	street	
			•			
Description of Monum Location of this Point		Monument or A	occessories	Established	by-You	to Perpetuate the
nothing set						
Sketch showing Relati Found or Set. Show	ve Location of Supporting and/	Monument Acce or Contradictor	essories ar y Evidence	nd Two Refe where App	erence Po Hicable. I	oints Stating Whether nclude North Arrow.
NOT MONUMENTED	0818600240 WEST QTR S 2 T18S R8E SLM NOT MONUMEN			ECS RM C N 02'13'02" W		
Certification:						
Firm name and/or S	urveyor: Joha	nsen & Tuttle I	Eng.	Craig E.	Johansen	
Address: 90 South	100 East, Cas	tle Dale, Utah	84513		Phone:	<u>(435)</u> <u>381-2523</u>
This is to certify that of my knowledge the				k described in	this recor	d and that to the best
			(a.m		John.	ueen_
Location Diagram:			40000	Craig E.	Johanser	
Section: 29			•			SED LAND STAND
Township: 18 S. Range: 8 E.	<b></b> 2	9				No. 146602
Range: <u>8 E.</u>		200	20	Nov. 1	998	CRAIGE.