## EMERY COUNTY LAND SURVEY MONUMENT RECORD

| Date of field work: 1-2-01   | County F  | Reference No. <u>16(0100240</u>                                |
|--|---|--|
| Type of Monument:  | Section Corner X  |  |
|  | Bench Mark  | Other  |
| Your Description and Observation of M<br>FOUND 2 ECS RM CAPS ALON  |   | : H164W44  |
| Description of Monument, Reference M<br>Location of this Point:<br>557 A #4 전략   |   | ed by You to Perpetuate the                                    |
| Sketch showing Relative Location of M<br>Found or Set. Show Supporting and/o   | r Contradictory Evidence where Ap   | ference Points Stating Whether policable. Include North Arrow. |
| NOT NOT NONUMENTED  NO 402003  RM 59.12 Fr 14 25   30 7  RM 60.18  14 25   30 7  RM 60.18  14 25   30 7  RM 60.18  14 25   30 7  RM 59.12 Fr  15 25   30 7  RM 59.12 Fr  16 25   30 7  RM 59.12 Fr  17 25   30 7  RM 59.12 Fr  17 25   30 7  RM 59.12 Fr  18 25   30 7  RM 59.12 Fr  19 25   30 7  RM 59.12 FR  10 10 10 10 10 | 20018 B<br>2007 A/W<br>CAP  | 567 #4 REBAR 1 48°08'57"E 51.29                                |
| Thin siding diay of barroyon   | nsen & Tuttle Eng.  | D /475 : 01 0503   |
|  | e Dale, Utah 84513  | Phone: (435) 381-2523  |
| This is to certify that I was in responsible<br>of my knowledge the information presented  | charge of the surveying work described in the herein is true and correct. |  |
|  |   | SECO LAND SURPE  |
| Location Diagram: Section: 30 Township: 165 Range: 10E   | Carl  | No. 146602 CRAIGE. JOHANSEM                                    |
|  | Date  | 11-30-01   |