## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	4-07-97		County Reference	No. <u>0918700200</u>
Type of Monument:	X	Section Corner _ Bench Mark _	- L DANIEL DE MANTE	r Corner
Your Description and	Observation of	Monument Found ( B	e Specific ):	
Found Standard BLM	Cap, in a South	n and West fence cor	rner, South side of Co	unty road.
Description of Monum Location of this Point		Monument or Accesso	ries Established by Yo	u to Perpetuate the
Set #5 rebar South,	Northwest, North	neast, and West of M	onument.	
			and Two Reference Fence where Applicable.  Solve the second secon	Include North Arrow.
S. R8E R9E 03 S25 S30 S36 S31 1970 LAND MAN	0918700200 NW COR S 31 T18S R9E SLM STD. BLM CAP	N 85'34'07" W , 14.9 N SET #5 REBAR	S 04'41'29" E 19 SET #5 REBAR	
Certification:				
Firm name and/or Su Address: 90 South		sen & Tuttle Eng. le Dale, Utah 84513	Craig E. Johanse Phone:	
		e charge of the surveying ad herein is true and corre	work described in this reco	)
Section: 31			' U	ED LAND SUA
Township: <u>18 S.</u>	├ <u>3</u> 1			

Range: \_\_\_

## EMERY COUNTY LAND SURVEY MONUMENT RECORD

ENE	MY COOMIY	LAIND SURVEY	MOMOMEM! NECOND	
Date of field work:	3-27-97		County Reference No	o. <u>0918700140</u>
Type of Monument:		Section Corner	X Quarter Co	orner
	<u></u>	Bench Mark	Other	
Your Description and	Observation of	Monument Found (	Be Specific ):	
Found Standard BLM	Cap, 2.0' East	of a mound of sto	ne on the South edge of a	road.
Description of Monum Location of this Point		Monument or Acces	sories Established by You to	) Perpetuate the
Set #3 rebar North,	South, and Eas	t of Monument.		
		•		
		•		
Sketch showing Relati Found or Set. Show	ve Location of Supporting and,	Monument Accessor or Contradictory Ev	ies and Two Reference Poin idence where Applicable. Inc	ts Stating Whether lude North Arrow.
T18S R8E R9E 08  1/4  8 S36 S31  1970  LAND MANUSCRIPTOR  LAND MANUSCR	0918700140 WEST QTR S 31 T18S R9E SLM STD. BLM CAP	N 06-14'05" W SET #3 REBA	N 88°23'45" E,	14.30
Certification:				
Firm name and/or S	urveyor: Joha	nsen & Tuttle Eng.	Craig E. Johansen	
•		tle Dale, Utah 8451	3 Phone:	(435) 381-2523
		ole charge of the surveyi ted herein is true and co	ng work described in this record orrect.	and that to the best
			0 1/	7
	-	<u>(</u>	araig E. phan	yeu_
Location Diagram:	1		Craig E. Johansen	
Section: 31				SED LAND SURV
Township: <u>18 S.</u> Range: 9 E.	<b>•</b> 3	1	<b>]</b> [§	
	] 1	_	20 Nov. 1998	No. 146602 (**) CRAIG E.
	L1		Date A	IOHANGEN / //

NO TE OF UT