
EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	4-16-97		County	Reference	No	0818640200
Type of Monument:		Section Corner Bench Mark	X	Quarter Other	Corne	r
Your Description and	Observation of	Monument Found (1	Be Specific):			
Found two Standard l	ECS RM Caps					

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a $8" \times 3/8"$ spike in the road for the corner. Also set a #5 rebar northwest, and southwest of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:


Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
Section: 31
Township: 18 S.

Range: 8 E.



Craig E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	4-15-97		County Reference	No. 0818700200
Type of Monument:	X	Section Corner _ Bench Mark _	Quarter Other	Corner
Your Description and	Observation of N	Monument Found (B	e Specific):	
Found a Standard BLM	M Brass Cap in	an East-West-South	fence corner.	
Description of Monume Location of this Point		fonument or Accesso	ries Established by Yo	ı to Perpetuate the
Set a #5 rebar South	, West, and 2 #	5 rebars Southwest	of Monument.	
			and Two Reference F ence where Applicable.	
		SET #5 REBAR S 82"51"25" W .23.22		
OEPT OF INTER		, 125 W ,23.22		A
S? R7E R8E 9	0818700200 NW COR S 31 [18S R8E SLM	#5, REBAR 21	35 S 01 34 28" W	AR 20.42
	STD. BLM CAP	5 58 17 106 5 58 17 106	20.	
OF LAND MANIA		\$ \tag{\tag{\tag{\tag{\tag{\tag{\tag{		И
		63		
Certification:				
Firm name and/or Su			Craig E. Johanser	7
Address: 90 South	100 East, Castle	e Dale, Utah 84513	Phone:	(435) 381-2523
		charge of the surveying herein is true and corre	work described in this reco ect.	rd and that to the best
		سر	·	0
	•		cara E John	N. M. S. A. M. S. M. S. A. M. S. M. S. A. M. S.
Location Diagram: Section: 31	1 1	POSITION IN CONTRACT OF THE PO	Craig E./Johanse	STATE LAND SUPPLEMENT

Township:

Range:

18 S.

8 E.

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

TE OF UTP

EMERY COUNTY LAND SURVEY MONUMENT RECORD

		OOIIVEI WO			
Date of field work:	4-15-97		County Refe	erence No	0818700140
Type of Monument:		ion Corner		luarter Corne	er
	Benc	h Mark	C	other	
Your Description and	Observation of Monum	nent Found (Be	Specific):		
Found Standard BLM	Brass Cap in North—S	South fenceline.			
Description of Monum Location of this Point	ent, Reference Monum t:	ent or Accessorie	s Established l	oy You to P	erpetuate the
Set #5 rebar North,	Northwest, South, and	Southwest of Mo	nument.		
			•		
	ve Location of Monum Supporting and/or Cor	ntradictory Evidend	ce where Applic		
1/4) \ 2	0818700140 WEST QTR S 31 F18S PRE SIM S 8	N SET #5 REBAR	SET #5 N 05'36'34"	REBAR W ,12.96	
Certification: .					
Firm name and/or Su	ırveyor:Johansen &	Tuttle Ena.	Craig E. Joh	nansen	
	100 East, Castle Dale		**************************************	hone: <u>(43</u> 5	5) 381–2523
This is to certify that of my knowledge the	l was in responsible charge information presented hereir	e of the surveying wo n is true and correct.	rk described in thi	is record and t	hat to the best
Location Diagram: Section: 31 Township: 18 S. Range: 8 E.	31	20	Jraig E. Jo Jraig E. Jo Nov. 1999 Date		LAND SURPLES D. 146602 RAIG E. HANSEN