

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-6-2000

County Reference No. 0917 700 200


Type of Monument: ✓ Section Corner Quarter Corner
 Bench Mark Other

Your Description and Observation of Monument Found (Be Specific):
FOUND ONE ECS RM CAP. OTHER IS BROKE OFF

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

RESET NORTH RM
SET #4 REBAR SOUTHWEST, AND NORTHWEST OF THE MONUMENT

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.


Location Diagram:

Section: 31
 Township: 17S
 Range: 9E



Craig E. Johansen
 Craig E. Johansen

2-15-00
 Date



EMERY COUNTY LAND SURVEY MONUMENT RECORD


Date of field work: 2-1-99 County Reference No. 0917700/40
 Type of Monument: _____ Section Corner X Quarter Corner _____
 _____ Bench Mark _____ Other _____

Your Description and Observation of Monument Found (Be Specific):

Found Two Emery County Surveys Cap RMs, Along the East R.O.W Fence of U-10

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.


Location Diagram:

Section: 31
 Township: 17s
 Range: 9E



Craig E. Johansen
 Craig E. Johansen

2-15-00
 Date




EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-26-99 County Reference No. 0917640200
 Type of Monument: _____ Section Corner X Quarter Corner _____
 _____ Bench Mark _____ Other _____

Your Description and Observation of Monument Found (Be Specific):
FOUND STANDARD ECS CAP AT A NORTH, EAST, WEST FENCE CORNER
FOUND #5 REBAR WITH A 1" ALUMINUM CAP 0⁵ EAST OF CAP
FOUND ORIGINAL ROCK ON THE WEST EDGE OF CAP

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:
SET 2-#5 REBARS NORTH OF THE MONUMENT
SET A #5 REBAR NORTHWEST AND WEST OF THE MONUMENT


Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:
 Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
 Section: 31
 Township: 17S
 Range: 9E



Craig E. Johansen
 Craig E. Johansen

2-15-00
 Date

