
EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date	of	field work:	DEC 7 1999		County Re	eference	No. <u>0917440 200</u>
Туре	of	Monument:		Section Corner _ Bench Mark _		Quarter Other _	Corner
Your Description and Observation of Monument Found (Be Specific): Found STD ECS CAP NORTH OF A EAST-WEST FENCE. 66' EAST OF HUNTINGTON CREEK							

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

SET A #4 REBAR EAST, SOUTHEAST, SOUTH, AND SOUTHWEST OF THE MONUMENT

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435)381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best

of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 33

Township: 17 s


Range:

No. 146602 CRAIG E. JOHANSEN

TE OF U

EMERY COUNTY LAND SURVEY MONUMENT RECORD						
Date of field work:	JAN 25 1999		County R	Reference No. <u>0911</u>	1500 200	
Type of Monument:		Section Corner Bench Mark		Quarter Corner Other		
Your Description and Found STD. ECS CAP		•	` .	REVEL PIT		
Description of Monum Location of this Point SET A #5 REBAR AL	<u>:</u>				etuate the	

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.






Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram: Section: 33 Township: 17 5

Range:



Johansen



EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	Jan 25 1999		County R	Reference	No. 0917500 140		
Type of Monument:		Section Corner Bench Mark		Quarter Other _	Corner		
Your Description and Observation of Monument Found (Be Specific): FOUND THE ECS CAP ALONG A MORTH-SOUTH FENCE. 252 SOUTH OF EAST-SOUTH FENCE CORNER							

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

SET A \$ REBAR NORTH, NORTH WEST, WEST, AND SOUTH WEST OF MONUMENT

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



SET # 5 REBAR

5 45-11-36 E

31.45

SET # 5 REBAR

5 0-47-18E

24.71

SET # 5 REBAR

N 39-50-17 E

21.24

SET # 5 REBAR

1 21-50-06 E

22.11

Certification:

Firm name and/or Surveyor: <u>Johansen & Tuttle Eng.</u>

Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513

Phone:

(435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section:

23

Township: 🔄 🖘 💲

Range:

t 👼

33----

Oraia E. Dohansen

2-15-00

No. 146602 CRAIG E. JOHANSEN

ATE OF UTEN