| EME  | RY COUNTY LAND  | SURVEY MON   | umeni hec             | UHU                     |                   |
|--|---|--|-----------------------|-------------------------|-------------------|
| Date of field work:  | 4-21-97   |  | County Refere         | ence No. <u>09187</u>   | 00540             |
| Type of Monument:  |   |  |                       | arter Corner            |                   |
|  | Benci   | n Mark   | Oth                   | ner                     | <del></del>       |
| Your Description and   | Observation of Monum  | ent Found ( Be S   | Specific ):           |                         |                   |
| Found Standard ECS   | Cap in a east-west, o                                       | and northwest fend   | ce corner             |                         |                   |
| Description of Monume<br>Location of this Point  |   | ent or Accessories   | : Established by      | You to Perpetuc         | ite the           |
| Set a #5 rebar north   | , west, southwest, and                                      | I southeast of Mo  | nument                |                         |                   |
| Sketch showing Relative Found or Set. Show Stands 1/4 COUNTY SURE 1/4 COUNTY S | Supporting and/or Con                                       | tradictory Evidence  | SET #5<br>N 01'05'31" | ble. Include North      | Whether<br>Arrow. |
| R8E R9E  |   | 88'08'59" W , 17.37 (<br>SET #5 REBAR<br>36'34'42" W , 27.07<br>SET #5 REBAR |                       | 1" E , 25.94<br>5 REBAR |                   |
| Certification:   |   |  | •                     |                         |                   |
| Firm name and/or Su  | ırveyor: <u>Johansen &amp;</u>                              | Tuttle Eng.  | Craig E. Joha         | ınsen                   |                   |
| Address: 90 South  | 100 East, Castle Dale                                       | e, Utah 84513  | Ph                    | one: <u>(435) 381</u>   | <u>-2523</u>      |
|  | I was in responsible charge<br>information presented hereir |  | k described in this   | record and that to      | the best          |
|  |   | _ las  | nig E. Jo             | hausen                  |                   |
| Location Diagram:  |   |  | craig/E/Joho          | ansen                   | D.C.              |
| Section: 7   |   |  |                       | A SED LAN               |                   |
| Township: <u>18 S.</u><br>Range: 9 E.  | 7   |  |                       | No. 14                  | 6602              |
|  |   | 20   | Nov. 1998             | CRAI                    | GE.<br>ISEN       |

IE OF TO SUBSECTION OF THE PARTY OF T

## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-07-97 County Reference No. 0918700600

Type of Monument: X Section Corner Quarter Corner

Bench Mark Other

Your Description and Observation of Monument Found ( Be Specific ):

Found Standard BLM Cap, in North-South-East fence corner.


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set 2 #5 rebars in fenceline South, and 2 #5 rebars in fenceline East of Monument.

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0918700600 NW COR S 7 T18S R9E SLM STD. BLM CAP



Certification:

Firm name and/or Surveyor: \_\_ Johansen & Tuttle Eng. \_\_\_ Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 7
Township: 18 S.

Township: 18 S. Range: 9 E.

7----

*Rulia T. Dh.c.* Craig E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN