

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-26-98 County Reference No. 0720300540
 Type of Monument: _____ Section Corner X Quarter Corner
 _____ Bench Mark _____ Other _____


Your Description and Observation of Monument Found (Be Specific):

Found two Standard ECS RM Caps along south side of Bench Road,
 Measured and found a spike in the road

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #4 rebar north, and northeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
 Section: 11
 Township: 20 S.
 Range: 7 E.



Craig E. Johansen
 Craig E. Johansen
 No. 146602
 CRAIG E. JOHANSEN
 STATE OF UTAH
 20 Nov. 98
 Date

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-26-98 County Reference No. 0720300600
 Type of Monument: X Section Corner Quarter Corner
 Bench Mark Other


Your Description and Observation of Monument Found (Be Specific):

Found Standard ECS Cap 6' ± west of a east-west-south fence corner


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #4 rebar north, west, and two northeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0720300600
 NW COR S 11
 T20S R7E SLM
 STD. ECS CAP




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
 Section: 11
 Township: 20 S.
 Range: 7 E.



Craig E. Johansen
 Craig E. Johansen

20 Nov. 1998
 Date



EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-26-98 County Reference No. 0720240600

Type of Monument: Section Corner X Quarter Corner
 Bench Mark Other


Your Description and Observation of Monument Found (Be Specific):

Found Standard ECS Cap at a north-east-west fence corner

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set two #4 rebars north, and west of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 11

Township: 20 S.

Range: 7 E.



Craig E. Johansen
 Craig E. Johansen
 No. 146602
CRAIG E. JOHANSEN
 STATE OF UTAH
30 Nov. 1998
 Date