EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	1-19-98		County Refere	nce No. <u>0720400200</u>
Type of Monument:		etion Corner	Qua Oth	rter Corner er
Your Description and	Observation of Monu	ment Found (Be	Specific):	
Found Standard BLM (Cap 65'± south of	a west-north fence	e corner	
Description of Monume Location of this Point: Set a #4 rebar north,				You to Perpetuate the
				e Points Stating Whether le. Include North Arrow.
S T20S R7E T2 S T20S R7E T2 S28 S27 S33 S34 1962 LAND WANTE	0720400200 NW COR S 34 T2OS R7E SLM STD. BLM CAP	SET #4 REBAR S 83'04'53" W 11.71' S 40'52'38" W 19.38' SET #4 REBAR	SET #4 RE N 03'42'30" W S 56'17'2 SET #4	12.99' 9" E 17.19'
Certification:				
Firm name and/or Su	rveyor:Johansen_	& Tuttle Eng.	Craig E. Johar	ısen
Address: 90 South	100 East, Castle Do	ole, Utah 84513	Pho	ne: <u>(801)</u> 381-2523
	l was in responsible char nformation presented her			record and that to the best
Location Diagram:	i		Craig E. Joha	nsen
Section: 34			1 0	SO LAND STORM
Township: 20 S.	3,4		į	1/5/ No 146602 1/2/18
Range: <u>7 E.</u>		_20	Date 1918	CRAIG E. JOHANSEN