

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: DEC 2 1999 County Reference No. 0917340500

Type of Monument: _____ Section Corner Quarter Corner
 _____ Bench Mark _____ Other _____



Your Description and Observation of Monument Found (Be Specific):

FOUND STD BLM CAD ALONG A EAST-WEST FENCE

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

SET TWO #5 REBAR SOUTH EAST, AND TWO SOUTH WEST OF THE MONUMENT

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:


Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.


Location Diagram:

Section: 15
 Township: 17 S
 Range: 9 E



Craig E. Johansen
 Craig E. Johansen

2-15-00
 Date



EMERY COUNTY LAND SURVEY MONUMENT RECORD



Date of field work: DEC 6 1999 County Reference No. 09 17 400 500

Type of Monument: ✓ Section Corner Quarter Corner
 Bench Mark Other

Your Description and Observation of Monument Found (Be Specific):
 FOUND STD BLM CAP AT A EAST WEST SOUTH FENCE CORNER ALONG THE TOE OF A HILL

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:
 SET A #5 REBAR SOUTH, WEST, AND TWO SOUTH WEST OF THE MONUMENT


Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:
 Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
 Section: 15
 Township: 17 S
 Range: 9 E



Craig E. Johansen
 Craig E. Johansen

2-15-00
 Date



EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: FEB 3 1999 County Reference No. 0917400440

Type of Monument: _____ Section Corner ✓ Quarter Corner
 _____ Bench Mark _____ Other _____



Your Description and Observation of Monument Found (Be Specific):

FOUND STD ELS CAP NORTH of Highway 155

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

SET A #4 REBAR NORTHEAST, NORTH, NORTHWEST, AND WEST OF THE MONUMENT

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:


Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 15
 Township: 17 S
 Range: 9 E



Craig E. Johansen
 Craig E. Johansen

2-15-00
 Date

