EMERY COUNTY, UTAH - SURVEY MONUMENT RECORD

SKETCH SHOWING RELATIVE LOCATION OF MONUMENT, ACCESSORIES AND REFERENCE POINTS STATING WHETHER FOUND OR SET.

South 1/4 Corner of Section 35, T15S, R12E, S.L.B.&M. (Set Marked Stone)

S89°22'40"W 858.02'

Southeast Corner of Section 34, T15S, R12E, S.L.B.&M. (Set Marked Stone)

N89°27'40"E 1787.71'

The monument for this Closing Corner is a 2.5" 1913 G.L.O. Brass Cap, on a 2" Iron Pipe, protruding ± 20 " above ground. This cap is incorrectly marked.

Date: 11-12-13 Not to Scale

Note:

The Markings on this Monument are Incorrectly Marked for its Location.

BLM POINT ID (GCDB): UT260160S0120E0 500700

UNITS = US SURVEY FOOT

COORDINATES DETERMINED FROM:

TRI-STATE OPUS CORRECTED NETWORK CONTROL SYSTEM

GEOID 03, NAVD 88 ELEVATION = 5424.54'

STATE PLANE COORDINATES

"UTAH COORDINATE SYSTEM 1983 CENTRAL ZONE"

NORTHING = 6977004.457

EASTING = 1908992.196

GEOGRAPHIC COORDINATES - NAD 83

LATITUDE = $N 39^{\circ}28'10.98"$

LONGITUDE = W $110^{\circ}32'54.90"$

ELLIPSOID HEIGHT = 5383.99'



Corner Monument Markings - Photo View or Stamping on Cap


ADDITIONAL INFORMATION

CERTIFICATION

This is to certify that this record was prepared from field notes of actual surveys made by me or under my direct supervision and that the same is true and correct to the best of my knowledge and belief.

PHOTO OF CORNER

Stacy Stewart Surveyor's Name (Please Print): Firm Name: Tri-State Land Surveying 180 N. Vernal Ave, Vernal, UT Firm Address:_ Utah License Number: 189377 Survey Date: 09-09-13 LOCATION DIAGRAM 1" = 1 Mile



goognamaaa SEC___3__ __T____16S__ <u>R 12E</u>, <u>S.L.</u> B&.M. SURVEYED BY: S.V.

DRAFTED BY: V.H.