EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	1-19-98		County 1	Reference 1	No. <u>0720600300</u>)
Type of Monument:		Section Corner Bench Mark		Quarter (Other	Corner	
Your Description and	Observation of Mo	onument Found (Be	Specific):			
Found Standard GLO	Сар					
Description of Monume Location of this Point	ent, Reference Mo :	onument or Accessori	es Establishe	ed by You	to Perpetuate the	;
Set a #4 rebar north,	southwest, wes	st, and southeast of	Monument			
Sketch showing Relativ Found or Set. Show S						
S19 S20 URV	0720600300 NW COR S29 I2OS R7E SLM STD, GLO CAP	N 78°50'27" W 20.8 SET #4 REBAR S 38°57'05" W 21 SET #4 REBAR	"	'55'39'' E 16. I #4 REBAR 45'19'52'' E SET #4 REBA	19.57'	
Certification: Firm name and/or Su	rvevor Johanse	en & Tuttle Eng	Crain F	Johansen		
•	• ———	Dale, Utah 84513	Ordig Er	Phone:	(801) 381-2523	 }
This is to certify that	l was in responsible	charge of the surveying w	ork described i	n this record	and that to the best	 :

Location Diagram:

Section: 29
Township: 20 S.

Range: 7 E.

-----29-----

of my knowledge the information presented herein is true and correct.

Eraig E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

CEOFU

EMERY	COUNTY L	AND SURVEY	' MONUME	NT RE	CORD
Date of field work:	1-19-98		County	Reference	No0720540300
Type of Monument:		Section Corner Bench Mark	X	Quarter Other	Corner
Your Description and	Observation of	Monument Found (Be Specific):		
Found Standard BLM	Сар				
Description of Monum Location of this Point Set a #4 rebar north	t:			ed by You	to Perpetuate the
Sketch showing Relati Found or Set. Show :	ve Location of Supporting and/	Monument Accessori or Contradictory Evi	es and Two Ro dence where A	eference Po pplicable. I	oints Stating Whether Include North Arrow.
1/4 S20 NO	720540300 DRTH QTR. S29 OS R7E SLM D. BLM CAP	N 70'46'40'' W SET #4 REB/ S 55'45'03'' W 22 SET #4 REBAR	IR O	58'39" E 11.2 #4 REBAR 31'17'19" E 1 SET #4 REBAR	Ň

Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 29

Township: 20 S.

Range: 7 E.

----29-----


Essage Johansen Craig E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

PE OF UTA

EMERY	COUNTY L	AND SURVEY	MONUMEN	IT RECOR	PD O
Date of field work:	1-23-98		County R	eference No	0720600240
Type of Monument:		Section Corner Bench Mark	X	Quarter Corn Other	
Your Description and	Observation of	Monument Found (Be Specific):		
Found Standard ECS Description of Monum Location of this Poin	ient, Reference				
Set a #4 rebar north	ı, southwest, v	vest, and southeast	of Monument		
Sketch showing Relati Found or Set. Show	ive Location of Supporting and/	Monument Accessorie or Contradictory Evid	es and Two Refe dence where App	erence Points olicable, Includ	Stating Whether e North Arrow.



0720600240 WEST QTR. S29 T20S R7E SLM STD. ECS CAP GAME TRAIL

N 81'58'37" W 15.91' O N 13'26'03" E 13.39'
SET #4 REBAR SET #4 REBAR

S 42'41'07" W 12.08' O S 19'59'53" E 13.22'
SET #4 REBAR SET #4 REBAR

X

Certification:

Firm name and/or Surveyor: <u>Johansen & Tuttle Eng.</u> Craig E. Johansen


Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 29
Township: 20 S.

Range: 7 E.



Eine E Johannen

70 Nov. 1998

