Date of field work: 5-30-0	<i>)</i>	County Reference No. 1708-400500
Type of Monument:	Section Corner	Quarter Corner
1)	 Bench Mark	Other
Your Description and Observa Found STD BLM CAP Along	tion of Monument Found (Be A Forth-South Fence	Specific):
Location of this Point:	Terence Monument or Accessor	ries Established by You to Perpetuate the
Sketch showing Relative Loca Found or Set. Show Supporti	tion of Monument Accessories ng and/or Contradictory Evide	and Two Reference Points Stating Whether ence where Applicable. Include North Arrow.
	1	l
	e anomalo altra	£
OF THE	л 5°07'17"Ē 22.93	KON SEINE
TITSEBE STE	N 9'23'15"E	
S 59 510		, γ
(S) (S) (S)	\mathcal{O}_{l}^{r}	•
AND MORPHET	56'14'12"E	Con CE 185
	5 2*30'45"E	e Rebail
	22.52	ķ.
Certification:	<i>y</i>	:
Firm name and/or Surveyor:	Johansen & Tuttle En	
Address: 90 S. 100 E.	. Castle Dale, Utah 8	84513 Phone: (435) 381-2523
This is to certify that I was in of my knowledge the information	responsible charge of the surveying on presented herein is true and corre	work described in this record and that to the best ect.
		SED LAND SUR
Location Diagram:		
Section: 10		No. 146602

Township: 175

Range:

	>
Type of Monument: Section Corner Quarter Corner	
Bench Mark Other Other	
Your Description and Observation of Monument Found (Be Specific): FOUND STD BLM CAP $Z^{\frac{d}{2}}$ West of a Abeth-South FONCE Line	
OF A NOFTH-SOUTH FENCE LINE	
Description of Monument, Reference Monument or Accessories Established by You to Perpetuate Location of this Point: SET TWO * 5 REBARS NORTHERST, AND TWO SOUTHERST OF THE MONUMENT.	the
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Wir Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Al	
x-x-x	
some and a second	
N9°04'12"5 14.55	
N 25°34'42"E	
5.76 0 SET SERVERS N	
5 20°22'53"E - X	
59°55'25"E X	
16.75	
Certification:	
Firm name and/or Surveyor: Johansen & Tuttle Eng.	
Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2	523
This is to certify that I was in responsible charge of the surveying work described in this record and that to the of my knowledge the information presented herein is true and correct.	best
SED LAND SUR	
Location Diagram:	
Location Diagram: Section: 10' No. 146602	
Location Diagram:	

Date of field work: 5-30-0/		County Reference	No. 1708400540
Type of Monument:	Section Corner	Quarte	r Corner
	Bench Mark	Other	
Your Description and Observation of Found STD 82M CAP WITH A MOUNT			
Description of Monument, Reference Location of this Point:			u to Perpetuate the
SET A#S REBAR South, so Then ST, e	PAST, AND NORTH EAST O	FThe MONUMENT	
Sketch showing Relative Location of Found or Set. Show Supporting and	Monument Accessories /or Contradictory Eviden	and Two Reference f ce where Applicable.	Points Stating Whether Include North Arrow.
		H62°28′16°€ 15.84	
51 510 51 510 51 510 51 51	511°07'43"E SE RE	551°43'19"E 0 17.02 1855	
Certification:			
	iansen & Tuttle Eng stle Dale, Utah 8		(435) 381-2523
This is to certify that I was in responsi of my knowledge the information presen	ble charge of the surveying w ted herein is true and correc	l.	
		ASSED III	ND SUR
Location Diagram:		No. 1	46602
Section: 10 Section: 171 Sectio		CRA	IG E
10#H3Hp	/]	WHA! JOHA	INSEM / /

Date of field work: 5-14-01		County Reference No. 1708 400560
Type of Monument:	Section Corner	Quarter Corner
	Bench Mark	Other 1/16 CORNER
Your Description and Observation of FOUND STD BLM CAP IN A NOUND		pecific):
Description of Monument, Reference Location of this Point: SETA**A REBAR NORTH, WEST. SOUTH NO		Established by You to Perpetuate the
Sketch showing Relative Location of Found or Set. Show Supporting and,	Monument Accessories and or Contradictory Evidence	d Two Reference Points Stating Whether where Applicable. Include North Arrow.
	и	14"29' 37"E
SP 1510 SP 1510 SP 1510 SP 1982 LOUD MY WHEN	82°10'18"E 14.82	13.34 \$ 26°37′16″E 16.42
Certification:		
Firm name and/or Surveyor:Joh	ansen & Tuttle Eng.	
Address: 90 S. 100 E. Cas	stle Dale, Utah 845	13 Phone: (435) 381-2523
This is to certify that I was in responsi of my knowledge the information presen	ble charge of the surveying work ted herein is true and correct.	described in this record and that to the best
Location Diagram: Section: 10 Township: 175 Range: BE	<i>ă</i>	No. 146602 CRAIO E. JOHANSEN

Date of field work:	5-14-01		County R	eference No. 1708444	9520
Type of Monument:		ction Corner nch Mark		Quarter Corner Other 116 CORNER	
Your Description and Found STA BLM CAT		·	Specific):		
Description of Monume Location of this Point SET 6. #4 RebAR No.	•			·	e the
Sketch showing Relative Found or Set. Show S					
5/16 510 5 1982 1982	N88°22'29*W 12.80 536*17'52"W 18.17		#4 eeb ^{ar} 5 18°21'00"E 24.79		
Certification: Firm name and/or Su	· · · · · · · · · · · · · · · · · · ·	n & Tuttle Eng		(175) 70	
		rge of the surveying w	ork described in	Phone: (435) 381— this record and that to the	

Type of Monument: Section Corner Quarter Corner	
Bench MarkOther	
Your Description and Observation of Monument Found (Be Specific):	
FOUND STD BLM CAP	
Description of Manument, Beforence Manument or Acceptances Established by You to Pernetuate th	е
Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:	•
SETA # 4REBAR NORTH, WEST, SOUTHWEST, and SOUTHERST OF The MONUMENT	
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whet	her
Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arro	w.
N 9°20'27° ω 3 16,03	
5 82°42'12"W 16.19 5 7175 RB E 5 10 5 214 5 510	
1982 346° 28'32"E	
57016'33"W 0 / 21.12	
REBAR REBAR	
Certification:	
Firm name and/or Surveyor:Johansen & Tuttle Eng. Address: 90 S. 100 E. Castle Dale, Utah 84513Phone:(435) 381-25	23
This is to certify that I was in responsible charge of the surveying work described in this record and that to the be of my knowledge the information presented herein is true and correct.	
ED LAND STA	
Location Diagram: Section: 10 No. 146602 Township: 175 No. 146602 CRAIG E JOHANSEN	
Range: BE Date Date 11-30	-01

()

Date of field work: 5-14-0	<u>/</u>	County Reference No. 1708	440 488
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other	
Your Description and Observa	tion of Monument Found (B	e Specific):	
FOUND STD BLM CAP MARK	ted 1/2 for sec. 10 only		
FOUND STD BLM CAP MARI	led 1/4 for sec 3 only En	IST OF THE MONUMENT	
Description of Monument, Ref. Location of this Point: SET A ** A Rebar No 2Th, SOUTH W		ries Established by You to Perpe	tuate the
Sketch showing Relative Local Found or Set. Show Supporting	tion of Monument Accessories ng and/or Contradictory Evid	s and Two Reference Points Stati ence where Applicable. Include No	ng Whether orth Arrow.
	N 7°21'13"W 24 Relar		
	11.54		
OF THE	A BLOWD BL	m cap	
15 T175 RBE	T Now N	89°2831'8 _ @ FOUND BLM CAP	
	N	23.11	
1982	522°44'52'W (o s	44°20'21'E	
Carly Made	9.88	16.74 STITSTAS	
1708440600	REBARS	1962	
		1708442600	
Certification:		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Firm name and/or Surveyor:	Johansen & Tuttle Er		
Address: 90 S. 100 E.	Castle Dale, Utah	84513 Phone: (435) 3	<u>81–2523</u>
This is to certify that I was in of my knowledge the informatio	responsible charge of the surveying n presented herein is true and corn	work described in this record and that ect.	to the best
		SED LAND SURE	•
Location Diagram:		No. 146602	
Section: <u>/0</u> Township: <u>/7</u>		CRAIG EN JOHARSEN	4
Range: 8E		tacked & to	fre
	_	Data Data	<u> </u>
<u></u>		Date	11-30-0