Date of field work: JAN :	5 <i>20</i> 00	County Re	eference No. <u>0817 140 50</u> 0
Type of Monument:	Section Co Bench Mai		Quarter Corner Other
Your Description and Observ Found 570 BLM CAP but			
Description of Monument, Re Location of this Point: Ser Two 4s REBARS West,			•
Sketch showing Relative Loca Found or Set. Show Support	ation of Monument Ad ing and/or Contradic	ccessories and Two Refer tory Evidence where Appl	rence Points Stating Whether icable. Include North Arrow.
552-47  552-47  43.6  57. TITS REE  1982  LAND MININGS  1982  LAND MININGS  1982			
Certification:	SET = 8 REDAR N 47-58-12 E*	,   4	
Firm name and/or Surveyor:	_	∤ Eng. Craig E. Jo	hansen
•	st, Castle Dale, Utah		Phone: <u>(435) 381-2523</u>
This is to certify that I was in of my knowledge the information	responsible charge of the n presented herein is true	surveying work described in the and correct.	nis record and that to the best
Location Diagram: Section: 13 Township: 17 s Range: 8 s	13	Caraig E./Jo Praig E./Jo Date	No. 146602 CRAYOR JOHANSEM

t= 1 ¥ 1 k= 1	000/4//	E WAS COLLAR	- I WONOWILIN		•	
Date of field work:	12-9-99		County	Reference N	10. <u>0817160</u>	) <i>500</i>
Type of Monument:		Section Corner		_ Quarter (	1.7	
		Bench Mark	X	_ Other <u>U</u>	JEST /16	W.C.
Your Description and Found STANDARD	Observation of BLM CAP AL	Monument Found ONG SOUTH BA	d ( Be Specific ): NK of CANAL			
Description of Monume Location of this Point	ent, Reference SET 2 井	Monument or Ac 4 REBARS	cessories Establish South wEST o	ned by You t F CORNER	o Perpetua	te the
Sketch showing Relative Found or Set. Show S	re Location of upporting and/	Monument Acces: or Contradictory	sories and Two Re Evidence where A	eference Poin pplicable. Inc	nts Stating Clude North	Whether Arrow.
S. TITS ROE ON THE STATE OF LAND MINISTER LAND MINISTER OF LAND MINISTER O	Mer di Walt	The state of the s	××			
Certification:	Kfg.					
Firm name and/or Sui	veyor: Johan	sen & Tuttle End	g. Craig E.	Johansen		
Address: 90 South	100 East, Casti	le Dale, Utah 84	513	Phone: <u>I</u>	<u>(435)</u> 381-	-2523
This is to certify that I of my knowledge the in	was in responsible formation presente	e charge of the surv d herein is true and	eying work described correct.	in this record a	ind that to th	e best
Location Diagram: Section: <u> 3</u> Township: <u> 7 5</u> Range: <u>8 E</u>	\3		Craig E. Craig E. Date	Johansen Johansen	No. 146 CRAIC JOHAN	€.

Date of field work:	12-8-99		County Ref	erence No. <u>08</u> 1	7 <u>700 500</u>
Type of Monument:	X	Section Corner Bench Mark		Quarter Corner Other	
Your Description and FOUND STAN		Monument Found ( I		of ADAM	
Description of Monum Location of this Poin	" SET 2#4	Monument or Accesso FREBARS South FREBARS SOUTT	EAST	by You to Perpet	uate the
Sketch showing Relati Found or Set. Show	ve Location of Supporting and/	Monument Accessorie or Contradictory Evid	s and Two Refere ence where Applic	nce Points Statin able. Include Nor	g Whether th Arrow.
5. TITS R 8 E R 9 5 11 512 1 5 14 513 CM LAND WANTS	-X -X -	POND DAM  LAUTED RATE  UNITY ROAD	23-17 M M M M M M M M M M M M M M M M M M M		
This is to certify that	100 East, Casti	sen & Tuttle Eng. le Dale, Utah 84513 e charge of the surveying d herein is true and corre	work described in this	hone: <u>(435)</u> 38	
Location Diagram: Section: 13 Township: 17 ≤ Range: 9 E	13		2-15-00 Date	nansen No. 146 CRAIC JOHAN	3 E.

Date of field work:	JANG 2000		County Re	eference No.	0817 200 440
Type of Monument:		Section Corner		Quarter Cor	ner
		Bench Mark		Other	
Your Description and	Observation of	Monument Found ( )	Be Specific ):		
Description of Monum Location of this Point SET A STANDARD ECS	t:		ories Established	by You to	Perpetuate the
	• •	-	THE MONUMENT		
SET A * 5 REBAR NORTH,	WEST, NORTHWEST	/	<i>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</i>		
Sketch showing Relativ					
Found or Set. Show S	Supporting and/	or Contradictory Evid	ence where Appl	icable. Includ	le North Arrow.
		·	SET #5 REBAR		
			50-41-50W		
COUNTY SURL		r <sup>u</sup> s rebar -03-01E	40		
(1) V4 C2	ä	19.64			y.
14 - 13		DAR .)			IN .
TITS REC RESET 1919	***************************************	SET . 30. 27 6			.`
		4x 19.	Î		
		TET#5 REBAR	<b>*</b>		
Certification:		N 6.41.47 E	<b>*</b>		
Firm name and/or Sur	rveyor: Johans	en & Tuttle Eng.	Craig E. Jo	hansen	
		e Dale, Utah 84513	ļ.	Phone: <u>(43</u>	5) 381- <b>2</b> 523
This is to certify that I	was in responsible	charge of the surveying	work described in th	nis record and	that to the best
		herein is true and corre			
				10	
		<i></i>	rug E.	Johan	ren
Location Diagram:			Craig E. Ja	nansen	ED LAND SUP
Section: 13			, ,		
Township: 17.5  Range: 8 =	#13 !				No. 146602
Range: 8 E			2-15-0		CRAIG E.

Date

Date of field work:	12-9-99		County F	Reference	No. <u>0817 200 <del>1</del>20</u>
Type of Monument:		Section Corner		Quarter	Corner
		Bench Mark	X	Other _	5 Y16
Your Description and	Observation of	Monument Found ( I	Be Specific ):		
FOUND STANDARD	BLM CAP 15	5 = F+ + NORTH OF	A North, So	utll, Wes	ST FENCE CORNER
			•	, ,	
Description of Monum Location of this Poin		Monument or Access	ories Establishe	d by You	to Perpetuate the
		NORTHEAST, EAST	TAND South	EAST OF	MONUMENT
	·	,	,		
	e				
Sketch showing Relati	ivo Location of	Manument Acceptario	a and Two Pof	oronoo Do	sinto Statina Whother
Found or Set. Show					
			•		
•		2 5 8	Sel#ARE	31E	
T OF		1 × 1 × 2	100		1
97175 R8E P		586	18172 Set#4		A
5 1/6	<u> </u>		a .	RBR	N.
SIA 513 E			E. C.		Á
OF 1983 MANAGO		<u> </u>	\$ 5 m		
	•		**************************************		
0 110 11					
Certification:					
Firm name and/or St Address: 90 South	-	sen & Tuttle Eng. le Dale, Utah 84513	Craig E	Johansen Phone:	(435) 381-2523
		e charge of the surveying od herein is true and corr		this record	and that to the best
			0	0 1	0
			raig E.	to he	anen
Location Diagram:			Craig Z.	dohansen	O LAND STA
Section:			. 0		The second of th
Township: Range:	13				No. 146602 \S
<b>.</b>	•		2-15-00	>	CRAIG E.
<b>L</b> <sup>1</sup>	<u> </u>		Date		