## UTAH LAND SURVEY MONUMENT RECORD

County EMERY	1808 County Reference No. <del>2210</del> 322
	country Installation 140. Galle 300.
1. Date of Field Work: 1-22-01	
2. Type of Monument:  (Check one)  Section Corn  Bench Mark	nerQuarter Corner Other
3. Your Description and Observation of Monum found 5TP BLM CAP ON The WEST Side of	ient Found (Be Specific): - Α ωης μ
4. Description of Monument, Reference Monume Location of this Point: SETA#4 REBAR NORT	ent or Accessories Established by You to Perpetuate the hwest, west, Southwest, AND Southeast of the M
. Sketch showing Relative Location of Monume Found or Set. Show Supporting and/or Contra	ent Accessories and Two Reference Points Stating Wheth Edictory Evidence where Applicable. Include North Arrov
N60°47'09'W 25.85	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
577°09'37"W 5	
524°59'06"W 5800 X.	
Certification: Firm Name and/or Surveyor: 10 HANSEN & TO	UTTLE ENG Phone: 435-381-252
100 E	surveying work described in this record and that to the best of
Location Diagram: Section: 16 Section: 185	SEND LAND SUR
8.5	Sign
Range: 6E	Surveyer's Seai CRAIG E.
A	_ 85 8

12. Diagram Coordinate from Master Index for

Townships: \_

11. Monument Inscription:

Report one monument per form. Type or use permanent black ink. Fill in all items.