## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Type of Monument:    Section Corner   Bench Mark   Other	Date of field work: 5/24/01	County Reference No. 1708203500	
Your Description and Observation of Monument Found ( Be Specific ):  FOUND STANDARD BLIM CAP FOR THE CORNER OF 184 17  FOUND STANDARD BLIM CAP FOR THE CORNER OF SECTIONS 7 8 TO THE WEST  Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:  SET *5 REBAR FOR THE CLOSING CORNER * 1708200500  Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.  134.70  SEC. 30  SEC. 45.30  SEC. 45.3	Type of Monument: X Section Con		
FOUND STANDARD BLM CAP FOR THE CLOSING LORNER OF 18 17  FOUND STANDARD BLM CAP FOR THE CLOSING CORNER OF SECTIONS 7 18 TO THE WEST  Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:  SET *5 REBAR FOR THE CLOSING CORNER # 1708200500  Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.  IN 81°07'43 W 105.30  S88°5241'W 118.15  Certification:  Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utoh 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17	Bench Mark	Other	
Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:  SET *5 REBAR FOR THE CLOSING CORNER # 1708200500  Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.  OR *6 RESULT *5 REBAR FOR THE CLOSING CORNER # 1708200500  Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.  OR *6***OF***130****USS *58***519***USS *58**519***USS	Your Description and Observation of Monument Found ( Be Specific ):		
Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:  SET **5 REBAR FOR THE CLOSING CORNER ** 1708200500  Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable, Include North Arrow.  IN 81°07'43  S88°51'91'  134.70  588°51'91'  134.70  588°5241'  114.43  518 518 517  Certification:  Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (4.35) 381–2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17	FOUND STANDARD BLM CAP FOR THE CORNER OF 18417		
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.  Set 134.70  Set 134.70  Certification:  Firm name and/or Surveyor:  Johansen & Tuttle Eng.  Address:  90 S. 100 E. Castle Dale, Utah 84513  Phone: (435) 381–2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17	FOUND STANDARD BLM CAP FOR THE CLOSING CORNER OF SECTIONS 7 8 TO THE WEST		
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.  Set 134.70  Set 134.70  Certification:  Firm name and/or Surveyor:  Address:  90 S. 100 E.  Castle Dale, Utah 84513  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section:  17			
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.  If 81°07'43\top 105.30  S88°51'59"\top 134.70  S88°52'41"\top 114.43  S88°52'	Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:		
Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Artow.    R8(*07'43\times)	SET #5 REBAR FOR THE CLOSING CORNER # 1708200500		
Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Artow.    R8(*07'43\times)			
Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Artow.  If 81°07'43 \( \text{ic5.30} \)  S80°51'59' \( \text{ic5.30} \)  S80°524!'\( \text{ic5.30} \)  Certification:  Firm name and/or Surveyor:  Address: 90 S. 100 E. Castle Dale. Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17			
Certification:  Firm name and/or Surveyor:  Address:  90 S. 100 E.  Castle Dale, Utah 84513  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location:  134.70  588°52'41"  114.43  118.15  Castle Dale, Utah 84513  Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location:  17  No. 146602  CRAIG E.  CRAIG E.	Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.		
Sep 51/58   517   588 51/58   134.70		N 81°07'43W	
Certification:  Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17	(er)	105,30	
Certification:  Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17	7.67 1/1/2 1/10 1/10 1/10 1/10 1/10 1/10 1/1		
Certification:  Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17	(34.70)		
Certification:  Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17	518 517 CC 588	1°5241"W	
Certification:  Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17 No. 146602 CRAIG E.	57/58 \	and desired the same	
Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17  CRAIG E.	1		
Firm name and/or Surveyor: Johansen & Tuttle Eng.  Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17  No. 146602  CRAIG E.			
Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523  This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17  CRAIG E.	. ,	uttle Eng	
This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.  Location Diagram:  Section: 17  No. 146602  CRAIG E.	This hand diay or correspond	(177) 704 0507	
Location Diagram: Section: 17  Location Diagram:  CRAIG E.			
Location Diagram: Section: 17  No. 146602 CRAIG E.	of my knowledge the information presented herein is true and correct.		
Location Diagram: Section: 17  No. 146602 CRAIG E.	•	GED LAND SUR	
Section: 17 CRAIG E.	•	1/3/	
Range: 8E Cally Statement	Range: 8E	Cally & Johnson	