Date of field work:	4-14-97		County R	deference No. 0818500340
Type of Monument:		Section Corner Bench Mark	X	Quarter Corner Other
Your Description and	Observation of	Monument Found	(Be Specific):	
Found Standard BLM	Сар			
			•	
Description of Monume Location of this Point		Monument or Acce	essories Establishe	d by You to Perpetuate the
Set two #5 rebars so	uth, and a #5	rebar west, and i	north of Monumen	t
				erence Points Stating Whetl plicable. Include North Arro
S. DEPT OF INTERPOLATION OF LAND WANTED	0818500340 WEST QTR S 2 T18S R8E SLM STD. BLM CAP	И	R 18.53 SET # SET \$ SOTO	4" W , 35.26 5 REBAR 1 #5 REBAR 25'12" E , 25.99 #5 REBAR 9'45" E , 64.26
Certification:				
Firm name and/or Su Address: 90 South	-	nsen & Tuttle Eng. tle Dale, Utah 845		Johansen Phone: (435) 381-2523
		ole charge of the surve ted herein is true and		n this record and that to the bes
Location Diagram: Section: 21 Township: 18 S. Range: 8 E.	2		Carain E	Johansen Johansen Johansen No. 146602 CRAIG E. JOHANSEN

Date of field work:

4-11-97

County Reference No. 0818500400

Type of Monument:

χ

Section Corner

Bench Mark

Other

Quarter Corner

Your Description and Observation of Monument Found (Be Specific):

Found Standard BLM Cap with a mound of stone to the west


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, west, southwest, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818500400 NW COR S 21 T18S R8E SLM STD. BLM CAP



SET #5 REBAR N 03'33'22" E , 11.53

S 34'29'17" E . 25.55 SET #5 REBAR

Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng.

Craiq E. Johansen

90 South 100 East, Castle Dale, Utah 84513

Phone:

(435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section:

21

Township:

18 S.

Range:

8 E.

No. 146602 CRAM E. JOHANSEN

Date	of field work:	4-11-97		County	Reference	No. <u>0818440400</u>
Туре	of Monument:	1000	Section Corner Bench Mark	<u>X</u>	Quarter Other	Corner
Your	Description and	Observation of M	Monument Found (Be Specific):		

Found Standard BLM Cap at a north-south-east fence corner


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, northwest, southwest, and east of Monument


Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818440400 NORTH QTR S 21 T18S R8E SLM STD. BLM CAP



S 47'43'06" W , 21.96 SET #5 REBAR



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen


Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 21
Township: 18 S.

Range: 8 E.



Graig E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN

TOFUL

County Reference No. 0818420300 Date of field work: 4-10-97 Type of Monument: Section Corner Quarter Corner Χ EAST 1/16 Other Bench Mark Your Description and Observation of Monument Found (Be Specific):

Found Standard BLM Cap with a mound of stone to the north

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar north, northwest, west, and southwest of Monument

T18S R8E SLM


STD. BLM CAP

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.

SET #5 REBAR



N 86'39'44" W , 50.72 SET #5 REBAR 0818420300



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

(435) 381-2523 Phone: Address: 90 South 100 East, Castle Dale, Utah 84513

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 21 Township: 18 S.

Range: 8 E.

20 Nov. 1998

No. 146602 CRAIG E. **JOHA**NSEI

EME	RY COUNTY	LAND SURVI	EY MONU	MENT I	RECORI	ס
Date of field work:	4-10-97			County F	Reference	No. 0818440300
Type of Monument:		Section Corne	r	X		Corner
		Bench Mark			Other _	
Your Description and	Observation of	Monument Foun	nd (Be Spe	ecific):		
Found Standard BLM	Cap					
Description of Monume Location of this Point		Monument or Ad	ccessories (Establishe	ed by You	to Perpetuate the
Set a #5 rebar north,	, west, southwe	est, and southed	ast of Monu	ıment		
Sketch showing Relative Found or Set. Show S						_
			/			
			/& / 5: /	9/		ŧ
ESTEPT OF WIEND			/	o N	09'14'36" SET #5 R	E , 15.95
1/4 S21 S28 S	0818440300 SOUTH QTR S T18S R8E SL	5 21	T #5 REBAR 6'45" W , 12.4	2 0		N
The same of the sa	STD. BLM CAF	P S 49"	12'07" W , 16 T #5 REBAR	.69 b	S 18'19'16' SET #5	' E . 17.22 REBAR
LAND MA						
		//				
Certification:		/ /				
Firm name and/or Su	-			Craig E.	Johansen	
Address: 90 South	100 East, Cas	tle Dale, Utah 8	34513		Phone:	(435) 381-2523
This is to certify that of my knowledge the i	•	_	, .	described in	n this recor	d and that to the best
			(0100	م پر	Joseph	
Location Diagram:			Sem	Graig E.	Johanser	7
Section: 21			•			SSOLANDSU
Township: 18 S. Range: 8 E.	2	1				No. 146602
			20	Nov. Date	1998	CRAIG E. JOHANSEN

CRAIG E. JOHANSEN (VE OF UT