Date of field work: <u>5-</u>	7-6/	County Reference No. 1709440300
Type of Monument:	Section Corner	Quarter Corner
	Bench Mark	Other
Your Description and Obs	servation of Monument Found (Be Specific):
FOUND STD. BLM CAP 15	50't west of a Northwest-S.	ortheast Fence Line
Description of Monument,	Reference Monument or Access	sories Established by You to Perpetuate the
Location of this Point:	est, southwest, and southeast of	The MONUMENT
The first the state of the stat	,	
Sketch showing Relative	Location of Monument Accessori	es and Two Reference Points Stating Whether
Found or Set. Show Supp	porting and/or Contradictory Evi	idence where Applicable. Include North Arrow.
		' ;
	N 10	°00°38"5 23.32
EST. OF The	SET REDAY ->!	V3.5E
NTITIS ROE THE		`\
3 4 522 3 4 527 4	1 N77'08'48'W	· · · · · · · · · · · · · · · · · · ·
E 1869 13	N 12.70	,
CAND THURS		5 22°44'03"E
	550°34'02"W ./ ',	21.15
	SET*4	
Certification:	RESAR	_
Firm name and/or Surve		
Address: <u>90 S. 100</u>		
This is to certify that I we	as in responsible charge of the surveyir mation presented herein is true and co	ng work described in this record and that to the best prect.
Of the knowledge are time.	medon productor neven to the size	
		SED LAND SURV
Location Diagram:		
Section: 22		No. 146602 \ CRAIG E. \
Township: 175	22	JOHANSEN Inner
Range: 9E		(10-30
	<u> </u>	Date

Date of field work:	DEC 7 1999		County R	eference	No. 09 17 400 340
Type of Monument:		Section Corner Bench Mark		Quarter Other _	Corner
Your Description and Found STD BLM CAP	Observation of leading To The		(Be Specific):		
Description of Monuma Location of this Point SET A #4 REBAR WORTH	: , North WEST, WE	ST AND SOUTHWEST	OF THE MONUMENT	-	·
Sketch showing Relative Found or Set. Show S					
	CET #4 REBAR 527-17-10 = • 42.99	•	SET #4 REBAR 316-32-48 W 28,79		
S. TITS ROSE TO THE SELECTION OF LAND MINISTER S	Cet#4rebar _79-22-46€ • 36:38	•	·		
	CET [±] 4 REBAR N 53-36-15 E 52.70				
Firm name and/or Su Address: <u>90 South</u>	-	sen & Tuttle Eng. le Dale, Utah 845		ohansen Phone:	(435) 381-2523
This is to certify that I of my knowledge the ir	was in responsibl formation presente	e charge of the surve ed herein is true and	ying work described in correct.	this record	and that to the best
Location Diagram: Section: <u>22</u> Township: <u>17 \$</u> Range: <u>9 £</u>	72.		Taxing E.	ohansen	No. 146602 CRAIG E. JOHANSEN

Date of field work:	DEC 2 1999		County Re	eference No. <u>09</u>	117340400
Type of Monument:		Section Corner Bench Mark		Quarter Corner Other	
		Monument Found (Ве uTh, West FEXCE CORNER	e Specific):		
Location of this Point SET A = 5 RESPR NORTH	: h, North EAST, EAST,	Monument or Accessor	Е ДОНИМЕНТ		•
		Monument Accessories or Contradictory Evider			
5. TITS R 9 = P.		SET #5 RESAR S 1-17-31 W * 27.06	≤E7 *5 % * \$38 -23 34,17	-34VI	
1969 MANAS LAND MANAS	Ç		• SET #5' 585 21.	17-53 W	
Certification:		*	SET #5 REEAR N 46-39.05 W 9,32		
Firm name and/or Su Address:			Craig E. Jo		704 0507
This is to certify that I	was in responsible	le Dale, Utah 84513 e charge of the surveying wand herein is true and correc	vork described in t		381-2523
Location Diagram: Section: 22 Township: 17 s Range: 9 E	22-		Craig E. J.	phansen No. 14	15518
 			2-15-00 Date	CRAI JOHA	IG E.

Date of field work:	Feb 3 1999		County Reference	. No. <u>09 17 400 400</u>
Type of Monument:		ection Corner ench Mark	Quarte Other	r Corner
Your Description and Found 5TD BLM CAP	Observation of Mon	ument Found (Be	Specific):	
Description of Monume Location of this Point SET A #4 REBAR NORTH, I				u to Perpetuate the
Sketch showing Relativ Found or Set. Show S	re Location of Monu Supporting and/or C	ument Accessories Contradictory Eviden	and Two Reference F ce where Applicable.	Points Stating Whether Include North Arrow.
SIGN SIS SEE SEE SEE SEE SEE SEE SEE SEE SEE	SET #4 REI 5 42-02-2 32.20 SET #4 R N 89-17 20.99	29 E	SET #4 REBAR 2-38-36 W 24.29	
Certification:				
Firm name and/or Su Address: 90 South	-		Craig E. Johansen	
This is to certify that I	100 East, Castle Down was in responsible character formation presented here	rge of the surveying wo ein is true and correct	<i>a</i>	(435) 381-2523 Id and that to the best
Location Diagram: Section: <u>22</u> Township: <u>175</u> Range: <u>9</u> E			Craig E. Johanser 2-15-00 Date	No. 146602 CRAIG E. JOHANSEN