County EMERY	_	County Reference No. <u>6817560360</u>
1. Date of Field Work:	1-4-01	·
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other 1/16 CORNER
3. Your Description and C Found STD. BLM CAP	Observation of Monument Found of Local South of South of Local Sou	and (Be Specific): OF A EAST-WEST-SOJTH FENCE CORNER
•		
4. Description of Monume: Location of this Point: SET A #4 REBARS SOUTH		Accessories Established by You to Perpetuate the
SET 2 4 REbars Sout	h west of CAP.	•
5. Sketch showing Relative Found or Set. Show Sup	Location of Monument Acce porting and/or Contradictory	essories and Two Reference Points Stating Whether Evidence where Applicable. Include North Arrow.
	 	_xxx
N 87°27'47"W 64.23 561°55'0	SET#47 REBAR	N
60:7l S	31°58'44"W REBAR X 5	7°03′53″6 70.39
6. Certification: Firm Name and/or Surveyor:		in & TUTTLE ENG Phone: 381-2523
Address:	90 5 100 E	CASTLE DALE UTAH
This is to certify that I was in my knowledge the information	responsible charge of the surveyin on presented herein is true and cor	g work described in this record and that to the best of
7. Location Diagram: 8. Section: 2 ³ 9. Township: 175	2 3	Sign yards to LAND SUPER
10. Range: 8E OF THE CALLED TO SERVICE TO S	A 213	Surveior's Seal CRAIG E
E/6 523 S26		Dale DE OF UTE
11. Monument Inscription:	12. Diagram Coordinate from Master Index for Townships:	Report one monument per form. Type or use permanent black ink. Fill in all items.

County EMERY		County Reference No. <u>6847 510320</u>
1. Date of Field Work:	1-4-01	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner V Other 1/16 CORNER
3. Your Description and O	bservation of Monument Fou t west of a North-Scuth 1	and (Ro Specific)
•		
4. Description of Monumer Location of this Point: Set a#4 REBAR North, A	nt, Reference Monument or A	ccessories Established by You to Perpetuate the
SET 1 2 #4 Rebars South	EAST of CAP	·
5. Sketch showing Relative Found or Set. Show Supp	Location of Monument Acce porting and/or Contradictory	ssories and Two Reference Points Stating Whether Evidence where Applicable. Include North Arrow.
	N 24°35′14″E 21.64 Set [#] †	
	N 88°52'35"E REDAR 12.85	CET CET
	544°51'05"E 20.98	N N
	5 36°38'46'5 41.95	REPAR > 1
:		`x
6. Certification:		
Firm Name and/or Surveyor: _ Address:	JOHANSEN & T 905 100E CASTLE	DALE UTAM Phone: 381-2523
This is to certify that I was in my knowledge the information		
7. Location Diagram: 8. Section: 23 9. Township: 17.5		SEED LAND SURLE
0. Range: 8E	2,3	Signadure No. 146602 No. 146602 Surveyor's Soal CRAIG E.
SE 1 5 23	2	(over signitule)JOHANSEN
1983	,	11-30-01
I. Monument Inscription:	12. Diagram Coordinate from Master Index for Townships:	Report one monument per form. Type or use permanent black ink. Fill in all items.

11. Monument Inscription:

FMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: <u>5-9.0/</u>		County Reference No. 1708560 340
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other 1/16 CORNER
Your Description and Observati FOUND STD BLM CAP	- Andrews - Andr	
Description of Monument, Refe Location of this Point: SET A STEEL SPIKE WEST, AND		ies Established by You to Perpetuate the
Sketch showing Relative Location Found or Set. Show Supporting	on of Monument Accessories g and/or Contradictory Evider	and Two Reference Points Stating Whether nce where Applicable. Include North Arrow.
C = 1/16 C C S 73 C C C S 73 C C C S 798 3 C C C C C C C C C C C C C C C C C C	\$ 298.09	1 348° 03'45"W X TO SPIKE 1 BS SPIKE 2 F HA100-29-00 H. dist 258,
Certification:	ķ 1 82	
Firm name and/or Surveyor:	Johansen & Tuttle Eng Castle Dale, Utah 8	g. 14513 Phone: <u>(435)</u> 381—2523
This is to certify that I was in re of my knowledge the information Location Diagram: Section: 23 Township: 175 Range: 8E	presented herein is true and correct	No. 146602 CRAIG E JOHANSHN CLAUSE TE ON 10 11-30 - 0

County EMERY		i708 County Reference No. <u>08#560360</u>
1. Date of Field Work:	1-4-01	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner VOther 1/16 CORNER
3. Your Description and O	bservation of Monument Four	nd (Be Specific):
		ccessories Established by You to Perpetuate the
SET A #4REbar NORTH EA	IST, NORTHWEST, WEST, AND SO	outh West of Monument
5. Sketch showing Relative Found or Set. Show Supp	Location of Monument Acces porting and/or Contradictory 1	sories and Two Reference Points Stating Whether Evidence where Applicable. Include North Arrow.
	N 19"19"31"W 32.74 SET#4 REDAR 189"25'56"W 13.62	N 27°34'23'& 39.14
Co. KoaD	55 31°21'45"W 26.31	N
Certification: Firm Name and/or Surveyor: _	JOHANSEN (TI	Phone: 381-2523
Address: This is to certify that I was in	90 5 100 G CASTU	E DALE UTAH
my knowledge the information Location Diagram: Section: 23	n presented herein is true and corr	ect.
Township: 175 Range: 8E	2 3	Signaum No. 146602 Surveyor Seri CRAIG E
5 NE 1/16 523	N	(over signaturi) JOHANSIN
E., 1983		Date Port
Monument Inscription:	12. Diagram Coordinate from Master Index for Townships:	Report one monument per form. Type or use permanent black ink. Fill in all items.

County EMBRY		1708 County Reference No. <u>9944540 340</u>
I. Date of Field Work:	1-4-61	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other
3. Your Description and (found STP BLM CAP WITH	Observation of Monument Found A POST Along Side	l (Be Specific):
•		
—— —	nt, Reference Monument or Acc	essories Established by You to Perpetuate the
5. Sketch showing Relative Found or Set. Show Sup	E Location of Monument Accesso porting and/or Contradictory E	ories and Two Reference Points Stating Whether vidence where Applicable. Include North Arrow.
УЗЕ А 55	PE PENAGE NO SE	3'05"E .09
л 86°38 36.4	5 Ox	$\sqrt{}$
54	SET #4 REBAR	
	44.19	
6. Certification: Firm Name and/or Surveyor: Address:	JOHANS 90 5 100 E	EN 1 TUTTLE ENG Phone: 381-2523
This is to certify that I was in my knowledge the information	responsible charge of the surveying won presented herein is true and correc	ork described in this record and that to the best of
7. Location Diagram: 8. Section: <u>£3</u> 9. Township: <u>i7S</u> 10. Range: <u>9 ɛ</u>	2.3	Signature No. 146602
C 14 5 23	2	Surveyor's Scal CRAIG E. (over Septiature CRAIG E. (over Septiature CRAIG E. Date Tropy Of the Control of th
1983 MARKET 1983	10.75	11-30-01
1. Monument Inscription:	12. Diagram Coordinate from Master Index for Townships:	Report one monument per form. Type or use permanent black ink. Fill in all items.

County EMERY		County R	1708 eference No. <u>6817 546 360</u>
1. Date of Field Work: 1	-4-01		
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other 1/16 Cokuer	
3. Your Description and Obfound STD 8LM CAP.	servation of Monument Fou	nd (Be Specific):	
4. Description of Monumen Location of this Point: SET A#4 REBAR NORTH, NO	t, Reference Monument or A		You to Perpetuate the
5. Sketch showing Relative Found or Set. Show Supp	Location of Monument Acce orting and/or Contradictory	ssories and Two Referenc Evidence where Applicab	e Points Stating Whether le. Include North Arrow.
N 30°30'13 49.18		N E°09' <i>EB" E</i> 38.94	
	H"W SET*4 REDAR		
545°58 37.4	'59"ω		
6. Certification:			
Firm Name and/or Surveyor: Address:	905 100 F	ANSEN'S TUTTLE ENG CASTLE DALE UTAH	Phone: 381-2523
This is to certify that I was in r my knowledge the information	esponsible charge of the surveying a presented herein is true and cor		and that to the best of
7. Location Diagram: 8. Section: £3 9. Township: /75 10. Range: 8 E	2.3		Signator No. 146602
C THE LOUIS REE	↑	le car	TOWN'S SEACRAIG E STRIPTIAN SEN
N/W SS3			Date EOF UT
1973 1980 11. Monument Inscription:	12. Diagram Coordinate from Master Index for Townships:	Type or use p	nonument per form. ermanent black ink. in all items.

County <u>EMERY</u>		1708 County Reference No. 484546300
Date of Field Work:	1-3-01	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other
3. Your Description and O	bservation of Monument Fo	and (Be Specific):
FOUND STD. BLM CAP.		
4. Description of Monumer Location of this Point:	it, Reference Monument or	Accessories Established by You to Perpetuate the
SETA#4 REDAR NORTH, NO	PTHWGST, WEST, AND SOUTHWE	ST DE The MANNING IT
,	Amount of the first of the firs	· · · · · · · · · · · · · · · · · · ·
Sketch showing Relative Found or Set. Show Supp	Location of Monument According and/or Contradictory	essories and Two Reference Points Stating Whether y Evidence where Applicable. Include North Arrow.
		15.46
	- \	♠
57 4 °3	38'27'W \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	۸/
40	1109	/γ
Se	#4 / / / / / / / / / / / / / / / / / / /	
7	S 36°02'10"u	
	59.67	
6. Certification: Firm Name and/or Surveyor:	love ven di	
Address:	JOHANSEN 9	DALE OTAH Phone: 361-2523
This is to certify that I was in r	esponsible charge as all a sur	
7. Location Diagram:	presented herein is true and co	TTECL
8. Section: <u>23</u> 9. Township: <u>/75</u>		O LANU.CO
10. Range: 8E	23	Signatives
S. DETT. OF THE THE	1 2	Surveiol Steano. 146602 (aver strature CRAIC E. Course & JOHANSEN, 1
\$26 \$ \$26 \$ \$1983 \$2	10. 72	Report one manument per form
11. Monument Inscription:	12. Diagram Coordinate from Master Index for Townships:	Report one monument per form. Type or use permanent black ink. Fill in all items.

County <u>EMERY</u>		County Reference No. <u>004754032</u>
1. Date of Field Work: 1-4-01		·
2. Type of Monument: (Check one)	— Section Corner — Bench Mark	Quarter Corner Other 1/16 CORNER
3. Your Description and Observa Found STD BLM CAP	tion of Monument F	Found (Be Specific):
Description of Monument, Refe Location of this Point: SET A # 4 REBAR NORTH, NORTHWES		or Accessories Established by You to Perpetuate the
. Sketch showing Relative Locati Found or Set. Show Supporting	ion of Monument Ac and/or Contradicto	ccessories and Two Reference Points Stating Whethory Evidence where Applicable. Include North Arro
N 43°26′40*ω 39 . ι ι	SET#4 REBAR	N 4°28'51" <i>E</i> 28.юв
н 89°01' 39 °W 29.17 Set [#] 4 Rebar	7	N
<i>5 45° 38' <u>1</u></i> 41.79		
Certification: Firm Name and/or Surveyor: Address:)OHANSEN 90 5 100 E	N 3 TUTTUE ENG Phone: 381-2523 CASTLE DALE UTAM
This is to certify that I was in responsi my knowledge the information prese	ible charge of the surve nted herein is true and	eying work described in this record and that to the best of correct.
Location Diagram: Section: $\frac{23}{175}$ Township: $\frac{175}{8 \epsilon}$ Range: $\frac{175}{8 \epsilon}$	2 3	Signature No. 146602 Surveyor's Seal CD AVC F

11. Monument Inscription:

12. Diagram Coordinate from Master Index for Townships:

County EMERY		1708 County Reference No. <u>6847,520</u> 340
1. Date of Field Work:	1-4-01	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other
3. Your Description and O FOUND STP BLM CAP	bservation of Monument Found	-
·····		ssories Established by You to Perpetuate the
SEI ATAREBAR NORTH-	Northwest- west- And Southwest o	OF MONUMENT
		•
5. Sketch showing Relative Found or Set. Show Sup	Location of Monument Accessor porting and/or Contradictory Evi	ries and Two Reference Points Stating Whether idence where Applicable. Include North Arrow.
	<i>5€</i> Т [#] 4	N 7°21°54°W
	N 53'42'03"W L RebAR >	20.07
	29.97	i
		Ť
5 <i>6</i> 7°.	ω''ει'7'	N
	95	
	A	
	SET. 4 REBAR	٠.
	o 533°17'30'ω 45.13	
6 Continue	-19/15	
6. Certification:	, t	
Firm Name and/or Surveyor:Address:		TUTTLE ENG Phone: 381-2523
Additess:	905 100 E CASTLE	S DALE UTAH
This is to certify that I was in my knowledge the information	responsible charge of the surveying wor on presented herein is true and correct.	rk described in this record and that to the best of
7. Location Diagram:	The state of the s	
8. Section: <u>23</u>		LAND SU
9. Township: <u>/75</u>		Sign
10. Range: <i>8 &</i>	23	- 77.07
OF THE TAN	A	Summa Elizabeth Allian
TITS ROE		(over strange) CRAIN E
in .	a(TOTAL STATE OF
/5' cc	\mathcal{N}	Gordan /
W16 523 H		Date OF UT
\ ₫		11-80-01
S. 1983 3	10 m;	-
TANKE TANK	12. Diagram Coordinate	Report one monument per form.
1 Monument Incominting	from Master Index for	Type or use permanent black ink.
1. Monument Inscription:	Townships:	Fill in all items.

County ENERY		1708 County Reference No. <u>97:7520</u>
1. Date of Field Work:	4-01	
2. Type of Monument: (Check one)	——Section Corner	Quarter Corner
(Check one)	Bench Mark	Other1/16 CORNER
3. Your Description and Obs	ervation of Monument	Found (Be Specific):
-		·
Description of Monument, Location of this Point: SET A#4 REBAR NORTH - NO	Reference Monument o	or Accessories Established by You to Perpetuate th
	•	
Classic Branch		
Found or Set. Show Suppo	ocation of Monument A rting and/or Contradict	Accessories and Two Reference Points Stating Whe cory Evidence where Applicable. Include North Arr
n 56°34'51 39.84	"W 55T #4 1	μ (9°58'03''ω 25.27
N 89°27'18" 25.24	w	
	SELMR	
	544°18'34"ω	
:	33.63	
Certification:		
irm Name and/or Surveyor:		Phone: 381-2523
		E CASTLE DALE LITHY
This is to certify that I was in rem my knowledge the information	sponsible charge of the surve presented herein is true and	eying work described in this record and that to the best of
Location Diagram:		
Section: <u>23</u> Township: <u>/⁷⁵</u>		- LANDS
	1 , 1	Signagnyc
.0171101110.		# 1.7/ NT. 1400
Range: BE	2 3	Surveyor & Solai CRAIG H (over significate JOHANSE
	2 3	Surveyof S Squi CRAIG E

12. Diagram Coordinate from Master Index for Townships:

11. Monument Inscription:

County EMERY		1708 County Reference No. <u>00/7520</u> 300
		Twicence Ito. Son 10 20 300
1. Date of Field Work:	-5-01	
2. Type of Monument:	——Section Corner	
(Check one)	Bench Mark	Quarter Corner Other ///b CORNER
3. Your Description and Ob	oservation of Monument	Found (Be Specific):
FOUND STD BLM CAP		
4. Description of Monumen Location of this Point:	t, Reference Monument	or Accessories Established by You to Perpetuate the
SET A#4 Rebar North - North	hwest- west-and south wes	it of maximum at
		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
		•
Sketch showing Relative Found or Set. Show Supp	Location of Monument .	Accessories and Two Reference Points Stating Whether tory Evidence where Applicable. Include North Arrow.
	∠ET [‡] ¢r	
	48'33"W SET 4 9.43 K PLBAL N	14°40′51″E
		22.61
ر والموارد المراد المرا	death a	7
567°21 32.5		./
5¢T ⁴ 4		<i>N</i>
PebAR	· · ·	
	538°56'41"W	
	51.63	
Certification:		
Firm Name and/or Surveyor:		IOHANGO & TITTLE FOR
Address:	905	JOHANSEN ! TUTTUE ENG Phone: 381-2523
This is to certify that I was in a		
my knowledge the information	esponsible charge of the surv	veying work described in this record and that to the best of
Location Diagram:		
Section: 23		ED LAND SU
	1 !	Signague
Township: 175	مسأيا	
Township: 17.5 0. Range: 8ε	23	_ /5/ No. 146602 \
Township: 17.5 0. Range: 8E	2 3	Surveyer s Stal CP AIC FA
Township: 17.5 D. Range: 8ε		
Township: 17.5 D. Range: 8E	2 3 N	Surveyer S Stal CP AIC FA

11. Monument Inscription:

12. Diagram Coordinate from Master Index for Townships:

County <u>EMERY</u>		(708) County Reference No. <u>6947520320</u>
1. Date of Field Work:	-5-01	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other 1/16 Corner
3. Your Description and Of	bservation of Monument Fo	ound (Be Specific):
		•
4. Description of Monumer Location of this Point:	t, Reference Monument or	Accessories Established by You to Perpetuate the
	Thwest, west, AUD Southwest	of monument
5. Sketch showing Relative Found or Set. Show Supp	Location of Monument According and/or Contradictor	essories and Two Reference Points Stating Whether y Evidence where Applicable. Include North Arrow.
N 28°43'16" ⁴ 25.03	O 55T#4 C ZEBAR * 0	3°41'14"E 20.35
N <i>B</i> 9°19'09"0 19.09	SET*4 Rebar	\mathcal{N}
	6 542°20'26"W 24.45	
3. Certification: Firm Name and/or Surveyor: Address:	905	JOHANSEN TUTTLE ENG Phone: 381-2523
This is to certify that I was in a my knowledge the informatio		no work described in this
. Location Diagram: . Section: 23 . Township: 175 0. Range: 8 =	2.3	Sign Waskin LAND SURVEY
SER OF THE ILLOW	N	Surveyor See No. 146602 (over irnature CRAIC E. JOHN MED)
523 1983		11. 30-01 DOF UT
CAND THEN ASE	12. Diagram Coordinate	

from Master Index for

Townships: _

11. Monument Inscription:

Type or use permanent black ink.

Fill in all items.

County <u>EMERY</u>		1708 County Reference No. <u>@8:75</u> 0360
1. Date of Field Work:	1-4-01	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other
B. Your Description and C	Observation of Monument Fo by A TWC Track Road	ound (Be Specific):
		Accessories Established by You to Perpetuate the
Sketch showing Relative Found or Set. Show Sup	e Location of Monument Acc porting and/or Contradictor	cessories and Two Reference Points Stating Whether y Evidence where Applicable. Include North Arrow.
		1 45.95 1 m.65,50,54 s
	 	1 - 0 K
	ر اب ان اب ان	55 ZE N.E0, S1.885
	05:24	
	m. L1,81.0 L N	16.85 EI#4 M.20144.04N
Certification: irm Name and/or Surveyor: _	,	EbAR
ddress:		N 4 TUTTLE ENG Phone: 381-2523 STLE DALE UTAH
This is to certify that I was in my knowledge the information		
Location Diagram:	on presented herein is true and co	OITECL.
Section: <u>£3</u> Sownship: <u>175</u>	•	Signature State
Range: 8E	<u> </u>	No. 146602 \\2\
TITS RBE THE		(over jama urfoHANSEN
522 523	N	Date TEOFUTE
1982 \$		11.30-01
CAND MANAGERATION	12. Diagram Coordinat	e Report one monument per form.

Type or use permanent black ink.

Fill in all items.

from Master Index for

Townships:

			County Reference No. <u>08:75003</u>
1. Date of Field Work: 1-	5-01		<u> </u>
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Co	rner
3. Your Description and Obs	servation of Monument l Some Rocks To The So	Found (Be Specifi orh	ic):
		·	
4. Description of Monument Location of this Point:	, Reference Monument o	r Accessories Est	ablished by You to Perpetuate the
SETA#4 RebAR NorTh - NOR	Th West-West-E Scuth West	of Monument	
Found or Set. Show Support of the State of t	8"ω N 8" N	ccessories and Tv ory Evidence whe Pu'27"E Z3.05	vo Reference Points Stating Whethere Applicable. Include North Arrow.
Certification: Firm Name and/or Surveyor:	JOHANSEN	9 Tuttle Eng	201 2527
Address:		STLE DALE UTA	
This is to certify that I was in remy knowledge the information	sponsible charge of the surve	ying work described	in this record and that to the best of
Location Diagram:	1	7	
Section: 23 Township: 175			Signature State
. Range: <u>8E</u>	4 - 2 3 -	-	Surger SNo. 146602
TITS RBE POR	T		over ignatueRAIG E
1523	N		Caraly Tondy
522 -			The Country of

11. Monument Inscription:

12. Diagram Coordinate from Master Index for Townships:

	County EMERY County Reference No. 66:75500 320
•	1. Date of Field Work: 1-5-01
	2. Type of Monument: Section Corner Quarter Corner (Check one) Bench Mark Other 1/16 CORNER
	3. Your Description and Observation of Monument Found (Be Specific): Found STD BLM CAP ON The NORTH SLOPE OF A hill
	4. Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point: SET A#4 REDAR NORTHWEST- WEST- AND SOUTHWEST OF CAP
	5. Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.
	122°00' 43"W SET#4 NIGORS' 26"E
)	N 87. 51.18 W 0
	350° 24' 19" W
	6. Certification: Firm Name and/or Surveyor: 905 100 E CASTLE DALE UTAH Phone: 381-2523
	This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.
•	7. Location Diagram: 8. Section: 23 9. Township: 175 10. Range: 8E 2 3 No. 146602
	Survivor See RAIG E. (oversignatujo HANSEN S // S
)	Day 523 11-30-0
	12. Diagram Coordinate Report one monument per form. Type or use permanent black ink.

Fill in all items.

11. Monument Inscription:

Townships:

County <u>EMERY</u>		C	ounty Reference No. <u>0847 500</u>
Date of Field Well. 1 4	n)		
1. Date of Field Work: 1-4	-01		
2. Type of Monument:	Section Corner	Quarter Corne	-
(Check one)	Bench Mark	Other	
Your Description and Obser	vation of Monument l	Found (Be Specific):	
,		•	
Description of Monument, F Location of this Point: SET A #4 REBAR NORTH - NO			
Sketch showing Relative Loc Found or Set. Show Support	cation of Monument A ing and/or Contradicto	ccessories and Two l ory Evidence where	Reference Points Stating Whe Applicable. Include North Arr
n 49°57' <i>5</i> 7	"ω 5ET#4	N 10°10'20"W	
4633	Z RebAR	<i>2</i> 9.58	
585°10'41"6		a	A
24.86	7)	-1112
SET# 4			N.
Reba	^k >>		, A
	525°54'41"W		
	39,36		
Certification:			
Certification: Firm Name and/or Surveyor:	MANKEN S	TUTTLE ENG	··· .
Address:	90 5 100 E CAS	THE DALE UTAH	Phone: <u>381-2523</u>
This is to certify that I was in			
This is to certify that I was in response my knowledge the information pr	onsible charge of the surve	ying work described in t	his record and that to the best of
Location Diagram:		COITECL	-
Section: 23			TAND
Township: 175	!		Sign the St. D
Range: <u>8 &</u>	2:3		#/S/
of The E	A 7		Survey of See No. 146602
OF TITS R BE			(over ignature CRAIG E.
3 4 5 9	VΙ		Caraca OHANSEN
	<u> </u>		
522 523			11-30 . OF UT

11. Monument Inscription: Town

12. Diagram Coordinate from Master Index for Townships: