
EMERY COUNTY LAND SURVEY MONUMENT RECORD

- 177 -		Caro Consen	alchaolaith i	RECORL	•
Date of field work:	4-9-97		County I	Reference	No. <u>0818300240</u>
Type of Monument:		Section Corner	X	Quarter	Corner
		Bench Mark		Other _	4
Your Description and	Observation of M	Monument Found (Be Specific):		
Found Standard ECS	Cap along the e	ast right—of—way	fence on county	road	
Description of Monume Location of this Point	ent, Reference M :	lonument or Acces	sories Establishe	ed by You	to Perpetuate the
Set a #5 rebar south	, southwest, wes	st, and northwest o	of Monument		
Sketch showing Relative Found or Set. Show S	re Location of M Tupporting and/o	fonument Accessori or Contradictory Evi .N 55:50'49" W , 70.81 SET #5 REBAR	dence where Ap	erence Po plicable. Ir	ints Stating Whether Iclude North Arrow.
1/4 27 + 26 1/4 27 + 26	0818300240 WEST QTR S 26 T18S R8E SLM STD. ECS CAP	S 88°29'53" W , 57.08 SET #5 REBAR S 59°41'05" W , 65.97 SET #5 REBAR		S 00'04'05 SET #5	W , 24.87 REBAR
Certification:			1 1 ;		
Firm name and/or Su	rveyor: <u>Johans</u>	en & Tuttle Eng.	Craig E.	Johansen	
Address: 90 South	100 East, Castle	e Dale, Utah 8451.	3	Phone:	(435) 381-2523
This is to certify that I of my knowledge the ir	was in responsible Iformation presented	charge of the surveyin herein is true and co	g work described in rrect.	this record	and that to the best

Location Diagram: Section: 26

Township: 18 S.

Range: 8 E.



20 Day 1998

No. 146602 CRAIG E. JOHANSEN

TE OF UT

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:

4-8-97

County Reference No. 0818240300

Type of Monument:

Section Corner

Bench Mark

Quarter Corner

Other


Your Description and Observation of Monument Found (Be Specific):

Found Standard ECS Cap at a east, west, and south fence corner


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar south, east, and northwest of Monument Also measured to a UDOT ROW Cap south west of the monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0818240300 NORTH QTR S26 T18S R8E SLM STD. ECS CAP



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng.

Craia E. Johansen

Address:

90 South 100 East, Castle Dale, Utah 84513

Phone:

(435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section:

26

Township:

18 S.

Range:

8 E.

No. 146602 CRAIG E.

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of	field work:	4-8-97		County	Reference	No.	0818300300
Type of	Monument:	X	Section Corner Bench Mark		_ Quarter _ Other _	Corn	er


Your Description and Observation of Monument Found (Be Specific):


Found Standard ECS Cap at a north-south-east fence corner

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #5 rebar east, south, southwest, and northwest of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.





Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 26
Township: 18 S.

Range: 8 E.

----26----

aray E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN