EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	1-20-99		County Refere	ence No. <u>0918 400 700</u>
Type of Monument:		Section Corner		arter Corner
		Bench Mark	Oth	er
Your Description and Fand STD BLM	Observation of Mc Cap, IN A Nort	onument Found (h-South Fence,	Be Specific): Leaning on a e	15° Angle to The west
Description of Monum Location of this Poin	L.			You to Perpetuate the
				e Points Stating Whether le. Include North Arrow.
5. CEPT OF INVERSED OF TITS R. 9E P. 90 P. 18'S 29'E P. 1969 LAND MATTER OF LAND		• Set #5 RBR • Set #5 RBR • Set #5 RBR	527-17-46W 38.2D 567-30-22W 30.42 N66-20-50W 33.80 N42-11.00W 46.51	
Certification:	71			†
	100 East, Castle	narge of the surveying		
Location Diagram: Section: 3 Township: 185 Range: 9E	3		graig E. Johan Graig E. Johan -15-00 Date	No. 146602 CRAIG E. JOHANSEN

ATE OF UT