

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-25-	·01	County Reference No. 1708 600 100
Type of Monument:	✓ Section Corner	Quarter Corner
7 1	Bench Mark	Other
Your Description and Observe Found 1/2 in Plastic CAP on Found A 6" PVC pipE Filled	A REBAR IN The Co. Road.	21/2" below The surface
	JORTHWEST, AND NORTHEAST OF	ssories Established by You to Perpetuate the
Sketch showing Relative Loca Found or Set. Show Support	ation of Monument Accessoring and/or Contradictory E	ries and Two Reference Points Stating Whether vidence where Applicable. Include North Arrow.
		married A
	μ̈́	44°23'45"W \ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	· ;	23.27 FT N43°04'26"E
	-× × ×	SET GOS RM
1/2" PLASTIC		FOUND I'M "PLASTIC CAP
CAPON	CO. ROAD	<u></u>
a# 4 REbAR		
* NOTE;		OX -XO FOUND 6" PUL PIPE FILLED WITH CONCETE MARKED AS Shown
SEE BACK	-x-xx-	MARKED AS ShowN
of sheet t Cap Markia	553°3605 W ~	REDAR
Certification:	36·00	\$ (8) ≥ 52°31'48"E 30.15
	Johansen & Tuttle	
Firm name and/or Surveyor: Address: 90 S. 100 E		84513 Phone: (435) 381-2523
Address: 90 S. 100 E	. Odske bale, otali	7 / 100 / 10
This is to certify that I was in of my knowledge the informati	n responsible charge of the survey ion presented herein is true and c	ving work described in this record and that to the best correct.
		GED LAND SUP.
Location Diagram:		(S)
Section: 35		No. 146602 \テー
Township: <u>/75</u>	35	CRAIG F
Range: 8E		Caralla Sur All Markey



NORTH WEST RM

1708600100 Sheet 2





The street of the street of the street of

والمراوية فيهم المعاومة


EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: <u>5-7</u>	01		County R	leference No. 🚁	1708540100
Type of Monument:		Section Corner Bench Mark		Quarter Corner Other	
Your Description and Obse Noผย	rvation of M	onument Found (B	le Specific):		
Description of Monument, Location of this Point: SET A8"x 36" spike 2°± SET ASTO ECS RM CAP	North of th	e North sho, of co	o. Road by Po		
SET A#4 REDAR SOUTHEAS			,		
Sketch showing Relative Le Found or Set. Show Suppl	ocation of Morting and/o	onument Accessories r Contradictory Evid	ence where Ap	plicable. Include N	ting Whether lorth Arrow.
8, x 3%,		37.00	CO. ROAD	-x-x -x	H NOTE:
	_	SET ECS RM 55 SET ECS RM 52.80 FT 52.80 FT 52.80 FT	SET#4 7 REDAR 513°32'4	SET ELS RM 65,28 FT	Sheet For Cap Mark
Certification:		47.95	42,33		
Firm name and/or Survey Address:		isen & Tuttle Er e Dale, Utah	ng. 84513	Phone: (435)	381-2523
Address: 90 S. 100 This is to certify that I was of my knowledge the inform	in responsible	charge of the surveying	work described in		to the best
Location Diagram: Section: <u>35</u>				No. 1466 CRAIG	02 P
Township: <u>/75</u> Range: <u>8E</u>	55-		7	JOHANS)	whene





SOUTHWEST RM



5-18.

UTAH LAND SURVEY MONUMENT RECORD

			Count	(708 y Reference No. <u>6275∞70</u>
1. Date of Field Wo	ork: <u>/-5-0/</u>	·		•
2. Type of Monume (Check one)	nt: Section Bench	n Corner _ Mark _	Quarter Corner	
3. Your Description	and Observation of M of at a south-East-F	onument Fo	und (Be Specific):	
70000 000 1001 100	y a n som east y	-24CE COMPE		
•				
	nument, Reference Mo oint: st, and south of mont		Accessories Established	by You to Perpetuate the
		•		
E 01			•	
5. Sketch showing R. Found or Set. Show	elative Location of Mo w Supporting and/or C	nument Acce	essories and Two Refere	ence Points Stating Whether
		ontradictory	Lividence where Appli	ence Points Stating Whether cable. Include North Arrow.
	·			
			N 88"15"48"1	5
		6	5EE AR 79.13	A
		(e) ·		1
		17 - X	x = x = x = x	٨.(
	< 18(5°3(°12)		N 87"33"33"E	V
	51°15'31"W 31.24		N87"33'33"E AZ.7Z	Λ
	31.24	1 SET #4		Λ(
	31.24 5 <i>0°07'0</i> 8"W	X SET HA		/\
6. Certification	31.24	X SET HA		N
6. Certification: Firm Name and/or Surv	31.74 50°07'08"W 62.70	IX SET HA	42.72	N 425\301 2527
	31.24 5 0°07'08"W 62.70 (eyor: <u>Johansen</u> 4	X SET HA	42,72	Phone: <u>435)381-25</u> 23
Address: This is to certify that I	31.24 5 0°07'06" W 62.70 (eyor:	X SET #4 IX SET #4 IL REBAR X TUTTUE E	AZ.7Z NG NALE UT	
Firm Name and/or Surv Address: This is to certify that I	31.24 5 0°07'06" W 62.70 (eyor:	X SET #4 IX SET #4 IL REBAR X TUTTUE E	AZ.7Z NG NALE UT	
Firm Name and/or Surv Address: This is to certify that I my knowledge the infe	31.24 \$0°07'08"W 62.70 (eyor:	X SET #4 IX SET #4 IL REBAR X TUTTUE E	AZ.7Z NG NALE UT	ord and that to the best of
Firm Name and/or Surve Address: This is to certify that I my knowledge the information Diagram: Location: 35	31.24 5 0°07'06" W 62.70 (eyor:	X SET #4 IX SET #4 IL REBAR X TUTTUE E	AZ.7Z NG NALE UT	ord and that to the best of
Firm Name and/or Surve Address: This is to certify that I my knowledge the information Diagram: 3. Section: 35 Township: /75	31.24 5 0°07'06" W 62.70 Yeyor: JOMANSEN 4 90 5 100 E Was in responsible charge ormation presented herein	TOTTLE E	AZ.7Z NG NALE UT	ord and that to the best of
Firm Name and/or Surve Address: This is to certify that I my knowledge the information Diagram: 5. Section: 35 7. Township: 175	31.24 5 0°07'06" W 62.70 (eyor:	TOTTLE E	AZ.7Z NG NALE UT	ord and that to the best of

11. Monument Inscription:

12. Diagram Coordinate from Master Index for Townships:

Report one monument per form.

Type or use permanent black ink.

Fill in all items.

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-19-01	_	County Reference	No. 1708500140
Type of Monument:	Section Corner Bench Mark	Quarte Other	r Corner
Your Description and Observation of Found STD BLM Cap at the base	of Monument Found (Be S FOF A LAZGETTEC ONTHE	pecific): <i>No</i> хTA side	
Description of Monument, Reference Location of this Point: SETA * S REBAR NORTH, NORTH WEST, W			u to Ferpetuate the
Sketch showing Relative Location of Found or Set. Show Supporting and The	Monument Accessories ard/or Contradictory Evidence	10 Two Reference where Applicable. 10 Where Applicable. 11	Points Stating Whether Include North Arrow. "w
Certification:			
, , , , , , , , , , , , , , , , , , ,	ohansen & Tuttle Eng. Oostle Dale, Utah 845	513 Phone:	(435) 381-2523
This is to certify that I was in respon of my knowledge the information pres	sible charge of the surveying won ented herein is true and correct.	k described in this reco	ord and that to the best
Location Diagram: Section: 35: Township: 175 Range: 8E	35	No. CR	146602 SAIG-E. ANSED