

# EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 6-8-01

County Reference No. 1706200540

Type of Monument:            Section Corner             Quarter Corner  
           Bench Mark            Other           


Your Description and Observation of Monument Found ( Be Specific ):

FOUND STD FOREST SERVICE CAP

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

SET #5 REBAR NORTH, EAST, SOUTHEAST, AND SOUTHWEST OF THE MONUMENT

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng.  
 Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 8  
 Township: 17S  
 Range: 6E



\_\_\_\_\_  
 Date 11-30-01