## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 5-3-0/		County Reference No. 1709 200540
Type of Monument:	Section Corner	Quarter Corner
Type of Mondificity	Bench Mark	Other
		Santia ).
Your Description and Observation of Monument Found (Be Specific):		
FOUND STD. BLM CAP Along	a NORTH-SOUTH FENCE LINE	
Description of Monument, Ref Location of this Point:	erence Monument or Accessorie	es Established by You to Perpetuate the
SET 2#4 Rebars North, AN	ed South of the MONUMENT	
	- Total Contract	
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.		
	1 *	13"E 52 3E
	55 4 / No°42'	(90, 90, 90, 90
of The Jan	REDARS XX, NO 42'	23"W, 20.13
TIDS ROE TO	×	N
57/58	¥ Y	
1970	51°39'	25°E, 18.72
EAND MAR	SET AS I	
	RebAR 7 8 51030	'50" ë , 38.39
Certification:	\ <b>X</b>	
Firm name and/or Surveyor:  Address: 90 S. 100 E.		4513 Phone: (435) 381-2523
		ork described in this record and that to the best
of my knowledge the information	n presented herein is true and correct	t.
		SED LAND SUPPLY
Landian Diagrams		
Location Diagram: Section: 8		No. 146602 \S
Township: 175	8	CRAIG E.
Range: 9 E		Coral & John Shappen
		Date De OF UTIL