EMERY COUNTY LAND SURVEY MONUMENT RECORD

EIVIEI	TI CODIVI	LAIND SUNVEY I	ALCHADIAIEIA I L	IECOND	
Date of field work:	3-26-97	•	County R	eference No.	0819400600
Type of Monument:	X	Section Corner Bench Mark		Quarter Cor Other	ner .
Your Description and (Observation of	Monument Found (Be Specific):		
Set a 8" x 3/8" spik	e in roadway.	Measured from two	ECS RM caps.		
Description of Monume Location of this Point:		Monument or Acces	sories Established	d by You to	Perpetuate the
Set #5 rebar Southeas	st ,and Southw	est of Monument			
Sketch showing Relativ Found or Set. Show S	upporting and, 0819400600 NW COR S 1 T19S R8E SI SET SPIKE	or Contradictory Evi	FOUND ECS RM E . 17 58 75 FOUND ECS RM E . 17 58 FOUND ECS RM E . 17	olicable. Inclu	
Certification:	S 44 SET	#5 11	•		
This is to certify that I	100 East, Cas	nsen & Tuttle Eng. tle Dale, Utah 8451. le charge of the surveyir ed herein is true and co	ng work described in	Phone: <u>(</u> 4	35) 381-2523 If that to the best
Location Diagram: Section: 10 Township: 19 S. Range: 8 E.	1() -	JJ/9/9	Johan Johansen	<u></u>

EMERY COUNTY LAND SURVEY MONUMENT RECORD


Date	of field	d work:	<u>3-26-97</u>		C	County	Reference	No	0819400540
Туре	of Mor	nument:		Section Corner Bench Mark	<u>X</u>		Quarter Other	Corne	r ·
Your	Descrip	otion and	Observation	of Monument Found (Be Spec	cific):			

Found Standard UPL Cap, Southwest of a fence corner


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set #5 rebar North, Northeast, East, and Southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0819400540 WEST QTR S 10 T19S R8E SLM UPL CAP



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen


Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 10
Township: 19 S.

Range: 8 E.



Craig E. Johansen

12/9/97 Date

EME.	HY COUNTY	LAND SUHVEY	WONUMENI I	iecom!	J
Date of field work:	3-25-97	•	County F	Reference	No. <u>0819400500</u>
Type of Monument:	X			Quarter	Corner .
		Bench Mark		Other _	· ILLE LANGE CONTROL C
Your Description and	Observation of	Monument Found (Be Specific):		
Found Standard ECS	Cap .5 Ft East	of a steel Witness	post		
Description of Monume Location of this Point		Monument or Acces	sories Establishe	d by You	to Perpetuate the
Set two #5 rebars Sc	uthwest, and a	#5 rebar South, c	nd Southeast of	Monume	nt
Sketch showing Relative Found or Set. Show S					
COUNTY SUPERIOR TO THE PROPERTY OF THE PROPERT	0819400500 NW COR S 15 T19S R8E SLM STD. ECS CAP	S 585520 WEB S 585 20 WEB SET #5 REBAR SET #5 REBAR	S 12'35'39"		
Certification:		SET #5	SET #5		
Firm name and/or Su	ırveyor: <u>Johar</u>	nsen & Tuttle Eng.	Craig E.	Johansen	
Address: 90 South	100 East, Cast	tle Dale, Utah 8451	3	Phone:	<u>(435) 381–2523</u>
		le charge of the surveyi ed herein is true and co	orrect.		D
Location Diagram:			araig E.	Johanser Johanser	ausen
Section: 10			0	/	
Township: 19 S.	1'C)- — — -			

Range:

8 E.

EME	:RY COUNTY	LAND SURVEY	NONUMENI	HECOHL)
Date of field work:	3-25-97		County	Reference	No. <u>0819340600</u>
Type of Monument:		Section Corner	Χ	Quarter	Corner
		Bench Mark		Other _	
Your Description and	Observation of	Monument Found (Be Specific):		
Found Standard ECS	Cap in a N-S	fence, 35' South of	a W fence.		
Description of Monum Location of this Poin	ent, Reference t:	Monument or Acces	sories Establish	ed by You	to Perpetuate the
Set #5 rebar North,	South, and Nort	thwest of Monument			
Sketch showing Relati Found or Set. Show	ive Location of Supporting and/	Monument Accessori or Contradictory Evi	es and Two Re dence where A	eference Po pplicable. I	oints Stating Whether nclude North Arrow.
	N 3	SET #5 REBAR 7°07'16" W , 59.88	**************************************		
COUNTY SUPPLY OF THE SELM ASSAULT	0819340600 NORTH OTR S T19S R8E SL STD. ECS CAR	5 10 M	N 01.51.18	N 24.32 REBAR	
Certification:		•	1 *		
Firm name and/or Su	urveyor: Johan	sen & Tuttle Eng.	Craiq E.	Johansen	
	-	le Dale, Utah 84513	3	Phone:	(801) 381-2523
		e charge of the surveyined herein is true and co		in this record	and that to the best
Location Diagram: Section: <u>10</u> Township: <u>19 S.</u> Range: <u>8 E.</u>	10		Jaig E. Jajaj Date	Johansen 97	conen