Date of field work:	1-2-03	County Reference N	o. <u>2116600500</u>
Type of Monument:	Section Corner	Quarter (Corner
	Bench Mark	Other	
ORIGINAL SAND STO	servation of Monument Found (NE WITH 4 NOTCH'S O E AND 4 STEEL FENCE AS SHOWN.	N SOUTH FACE. 1	9 #6 RBAA \$
	Reference Monument or Access		to Perpetuate the
Sketch showing Relative Found or Set. Show Sup	Location of Monument Accessori porting and/or Contradictory Evi N	dence where Applicable. In 0 0 14°41	clude North Arrow. '55"w .75
OBIGINAL ROCK	0 0 2 0 548°14'5, 28.86	O O ROME ON ON	N69°56'11"E DO 24.86 CO D CROCKS) S'46'E 42
Certification:			
Firm name and/or Surve			435) 381-2523
Address: 90 S. 10 This is to certify that I we of my knowledge the info	as in responsible charge of the surveyir rmation presented herein is true and co	ng work described in this record	
Location Diagram: Section: 12 Township: 215	12	saig & John	No. 146602 CRAIG E. JOHANSEN
Range: 16E		8-20-03	The state of the s

	Date of field work:	7-2-03		County Re	ference No. <u>211660054</u>	0_
	Type of Monument:	Sec	ction Corner nch Mark		Quarter Corner Other	
	Your Description and	Observation of Mon	ument Found (Be	Specific):		
RET	•				AND CAP PLANTED	3
	•				PLANTED ALONG	
	THE NORTH, RO				,	JUE
	Description of Monum Location of this Poin	ent, Reference Monu t: places #4	iment or Accessor	ries Established 540ww	by You to Perpetuate t	he
	Sketch showing Relat Found or Set. Show	ive Location of Monu Supporting and/or C	ument Accessories contradictory Evide N N D	nce where Appl	rence Points Stating Whe licable. Include North Arr いい ロ テ ポイフ	OW.
	ORIGINE SANSTONE ROCK	<i>5 68°0</i> 1 33.0	'48"ω	57°09'38'E 30.80	l 74°57'58'E 25,98	
	Certification:					
	Firm name and/or S	urvevor: Johanse	en & Tuttle En	g.		
	Address: 90 S.		Dale, Utah 8	34513 F	Phone: <u>(435)</u> 381-25	<u>523</u>
	This is to certify that of my knowledge the	I was in responsible cha information presented he	arge of the surveying rein is true and corre	work described in ect.	this record and that to the b	est
				raig E.	LAND SV	
	Location Diagram: Section: 12			ang C.	No. 146602	

Date of field work:	7-2-03	(County Reference N	10. <u>2116600600</u>
Type of Monument:	Section Bench	n Corner Mark	Quarter (Corner
4"x 6" ORIG. A	Observation of Monume LOUK 4" OUT O EVIDENT NOTO IE	OF GROUND, W	ITH SURVEY E	
Description of Monume Location of this Point:	ent, Reference Monume FLACED 4 #4	nt or Accessories E	stablished by You	to Perpetuate the
Sketch showing Relative Found or Set. Show S	re Location of Monume Supporting and/or Cont	nt Accessories and radictory Evidence v	Two Reference Poi where Applicable. In	ints Stating Whether iclude North Arrow. 1
OBIGINAL RIXK	GROUND LEVEL		587°37'04'W	NO 28.90 1 DOCK 19.34 19.34 19.34 EVIDENCE 5 18°16'30"E 22.75
Certification:				
Firm name and/or Su Address: 90 S.		& Tuttle Eng. le, Utah 8451	3 Phone: _(435) 381-2523
This is to certify that of my knowledge the	I was in responsible charge information presented herein	of the surveying work of is true and correct.	lescribed in this record	and that to the best
Location Diagram: Section: 12 Township: 215 Range: 16E	2	8-20		No. 146602 CRAIG E. OHANSEN

Date of field work: 7-3-03		County Reference No. 2116620500
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other // LO CORNER
Your Description and Observation of #5 LeBar WITH STEEL FE		
Description of Monument, Reference Location of this Point: 357 4	Monument or Accessories E #A REBAL AS SIM	stablished by You to Perpetuate the
Sketch showing Relative Location of Found or Set. Show Supporting and,	Monument Accessories and for Contradictory Evidence	Two Reference Points Stating Whether where Applicable. Include North Arrow.
A N	N 20,21,33,00 S9.80 O	0 = #4 REPAR
REBAR 577° 39'51	•	° 38' 29' 'E 24. 36
Certification: Firm name and/or Surveyor:Joh	nansen & Tuttle Eng.	
	stle Dale, Utah 8451	3 Phone: (435) 381-2523
This is to certify that I was in responsi	ble charge of the surveying work ated herein is true and correct.	described in this record and that to the best
	Cerain	a for any hand and
Location Diagram: Section: 12 Township: 2)5 Range: 16E	V 8-20	No. 146602 CRAIG E. JOHANSEN
	1	Date

Date of field work: 8-1-03		County Reference No. 2116700 540
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other
Your Description and Observation of SET EM. CD. SURVE		ecific):
Location of this Point: SET	Monument or Accessories 4 #4 PEBAR TS STONE OSOUNS	
Sketch showing Relative Location of Found or Set. Show Supporting and	Monument Accessories and /or Contradictory Evidence	I Two Reference Points Stating Whether where Applicable. Include North Arrow. NO STAP RESERVE
(2015) (2015)	56,08 0 53,08	
Certification:		
	nansen & Tuttle Eng. stle Dale, Utah 845	13 Phone: (435) 381-2523
This is to certify that I was in respons of my knowledge the information presen	ible charge of the surveying work nted herein is true and correct.	described in this record and that to the best
Location Diagram: Section: 12 Township: 215 Range: 1915	2	No. 146602 CRAIG E. JOHANSEN Date ATE OF UTALL TO SURVIVE SERVICE ATE OF UTALL TO SURVIVE SERVICE ATE OF UTALL TO SURVIVE SERVICE TO SURVI

Date of field work:	7-2-03		County Reference	e No. <u>2116700600</u>
Type of Monument:	V	Section Corner		er Corner
		Bench Mark	Other	
Your Description and 12"X 6"X 12 0F STONE GROUND.	SANDSTON	E WITH DOSSIA	SLE 4 NOTCH.	LOOSE ON THE
Description of Monum Location of this Point	t: SET A #	t I REBAR 4	5 SHOWN.	
Sketch showing Relati Found or Set. Show	ve Location of M Supporting and/c	Monument Accessories or Contradictory Evide	and Two Reference ince where Applicable	Points Stating Whether Include North Arrow.
ROCK	1681° 31.28° W 1681° 31.28° W	N 12 12 30 5 12 12 12 12 12 12 12 12 12 12 12 12 12	0= #4 N89"&5'18"E 24.10	4 RESIDE
Certification:			_	
Firm name and/or S Address: 90 S.		nsen & Tuttle Er le Dale, Utah		(435) 381-2523
This is to certify that	t I was in responsible	e charge of the surveying od herein is true and corr	work described in this re	cord and that to the best
Location Diagram: Section: 12 Township: 215 Range: 16E	12		raig E. Joh.	No. 146602 CRAIG E. JOHANSEN
			8-20-03 Date	ATE OF UT AIT

Date of field work:	7-2-03	County i	Reference No. 2116640 500
Type of Monument:	Section Cor	ner V	Quarter Corner
type of worldment.	Bench Mark		Other
	· _		
Your Description and (Observation of Monument Fo	ound (Be Specific):	
PLASTIL SURVEY	CAP (UNLEGIBLE) WIT	H STEEL FENCE	S POST ON EAST SINE
	(
Description of Monume	ont Reference Monument or	Accessories Establish	ed by You to Perpetuate the
Location of this Point:	SET 4 #4 REBAR	A3 < 440 W20/:	,
Zoodkon ov akk	JET 4 CENTINO	1 1100-10	
Sketch showing Relativ	re Location of Monument Ac	cessories and Two Re	ference Points Stating Whether
Found or Set. Show S	Supporting and/or Contradict	tory Evidence where A	pplicable. Include North Arrow.
	4	√ 3°06'02"E	
	, ,	31.58	
		ι <i>Θ</i> ₹ ^γ	
	N85°51'10'W	a CAP DOST	
/ cap	22.36	30.00 588°38'4 30.89	2" <i>E</i> "
	ONKE	30.84	
	ν-	0	
		5 3°32'10"E	
		29.28	
Certification:			
	ırvevor: Johansen & T	uttle Eng.	
Firm name and/or Su		Utah 84513	Phone: (435) 381-2523
Address: 90 S.			
This is to certify that	I was in responsible charge of the	e surveying work described	in this record and that to the best
of my knowledge the i	information presented herein is tru	e and contect	
		1 6	LANDS
		Ceraig C	Charles
Location Diagram:		1	No. 146602
Section: 12			CRAIG E.
Township: 215			JOHANSEN /
Range: 16E		8-20-0	
		Date	A TE OF UTAT

Date of field work: $8-1-03$	County	Reference No. 216 640 540
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other <u>CENTER OF SE</u> CTIO
Your Description and Observation of SET EVY. W. SWAN.		:
Description of Monument, Reference Location of this Point: 5ET 4	Monument or Accessories Establis L #4 REBAL 193 SHOW	shed by You to Perpetuate the
Sketch showing Relative Location of Found or Set. Show Supporting and	Monument Accessories and Two 1 I/or Contradictory Evidence where 129°03'16"ω 26.29 © #4 1	Applicable: Illolade Herat Farsan
6.0.5. C14512 578°54'10 26.31	0 B N 47°55'40"E 26.94 0 552°24'03"E 24.82	
Address: 90 S. 100 E. Ca	nansen & Tuttle Eng. stle Dale, Utah 84513 sible charge of the surveying work describe	Phone: (435) $381-2523$ and that to the best
Location Diagram: Section: 12 Townsnip: 215 Range: 16E	Encus E 8-20.0 Date	No. 146602 CRAIG E. JOHANSEN

Date of field work: 7-2-03		County Reference No. 2116640600
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other
Your Description and Observation of I NO MONVMENT FOUND— CANS & POINT WITH NO O		ecific): OF LATHE, ROCKS; OLD TIN AROUND AREA.
January of this Deigh	Monument or Accessories # 4 REBINA AS	Established by You to Perpetuate the
Sketch showing Relative Location of I Found or Set. Show Supporting and/	or Contradictory Evidence	d Two Reference Points Stating Whether where Applicable. Include North Arrow.
EVINENCE OLD SWENTE, 010 SWENTE, 6- 572"54""W 28.60	NII°22'26"W 25.82 25.82 3.60°45'0 27.39 315°26'32"E 21.18	0 = #4 leban. 7"E
Certification:		
Firm name and/or Surveyor:Johc	ansen & Tuttle Eng. tle Dale, Utah 845	13 Phone: (435) 381-2523
This is to certify that I was in responsible of my knowledge the information presented.	le charge of the surveying work ed herein is true and correct.	described in this record and that to the best
Location Diagram: Section: 12 Township: 215 Range: 160	Lara	No. 146602 CRAIG E. JOHANSEN

Date of field work: 7-3-03		County Reference No. 2116660 500
Type of Monument:	Section Corner	Quarter Corner
	Bench Mark	0ther 241/16
Your Description and Observation of PLASTIC SURVEY CASE ON THE	Monument Found (Be 5 REGIAND , (CMA 14 5) DE OF CAA .	Specific): UNLEGIBLE) A STEEL FENC
	Monument or Accessorie	es Established by You to Perpetuate the
Sketch showing Relative Location of Found or Set. Show Supporting and	Monument Accessories of Contradictory Eviden	and Two Reference Points Stating Whether ce where Applicable. Include North Arrow.
	N 12°37'37"u	O = HA CERAR
	24.10	•
REBAR WITH 583'05'S CAP 24.23		
- 1 1		
Certification:		
	nansen & Tuttle Eng	
Address: 90 S. 100 E. Ca	stle Dale, Utah 84	4513 Phone: <u>(435)</u> 381-2523
This is to certify that I was in respons	ible charge of the surveying w	ork described in this record and that to the best
of my knowledge the information preser	ited herein is true and correct	t.
•	·	010
	Geri	ara & Mangro LAND STUDIO
Location Diagram:		
Section: 12		No. 146602 \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\
Township: 21:3	2	CRAIG E. JOHANSEN
Range: NE	C	20-03