## EMERY COUNTY LAND SURVEY MONUMENT RECORD

| Date of field work:<br>Type of Monument:                  | 1-27-98   | Section Corner<br>Bench Mark   | County<br>X    |  | No. <u>0720200540</u><br>Corner |
|---|---|--|----------------|--|---------------------------------|
| Your Description and                                      | Observation of  | Monument Found (   | Be Specific ): |  |                                 |
| Found Standard ECS  | Cap ontop of  | a hill in a mound  | of stone       |  |                                 |
| Description of Monum<br>Location of this Point            | <b>!:</b>   |  |                | ed by You  | to Perpetuate the               |
| Set a #4 rebar north                                      | , southwest, v  | vest, and southeast  | of Monument    |  |                                 |
| Sketch showing Relati<br>Found or Set. Show S             |   |  |                |  |                                 |
| SIT SIZ   | 0720200540<br>WEST QTR. S12<br>T20S R7E SLM<br>STD. ECS CAP | S 86'54'21" W 13<br>SET #4 REBAR<br>S 40'39'23" W 25<br>SET #4 REBAR | 5.71' \$       | 1'12'11" W 1<br>ET #4 REBAR<br>18'22'47" E<br>SET #4 REG | 26.20'                          |
| Certification: Firm name and/or St                        | urveyor: Joha   | nsen & Tuttle Eng.   | Craig E        | . Johanser   | ·                               |
|   |   | tle Dale, Utah 8451.   |                | Phone:   | (801) 381-2523                  |
|   |   | ole charge of the surveyir<br>ted herein is true and co              |                | in this recor  | d and that to the best          |
| Location Diagram: Section: 12 Township: 20 S. Range: 7 E. | •12   | 2  | Craia E        | CR   | 146602<br>AIG E.<br>IANSEN      |


## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-15-98 County Reference No. 0720140600 Type of Monument: Section Corner Quarter Corner Bench Mark Χ Other Witness Corner Your Description and Observation of Monument Found ( Be Specific ): Found Standard BLM WC Cap, 10ft ± north of an east-west fence Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point: Set a #4 rebar north, southeast, east, and southwest of Monument Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow. 0720140600 NORTH QTR. S12 WC - N 89'10'25" E 42.89' T20S R7E SLM STD. BLM CAP Certification: Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523 This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 12 Township: 20 S.

7 E. Ronge:



CRAIG E.


## EMERY COUNTY LAND SURVEY MONUMENT RECORD

| Date of field work:                            | 1-15-98   |   | County R                       | eference  | No. 0720200600         |
|--|---|---|--------------------------------|---|------------------------|
| Type of Monument:                              | X   | Section Corner<br>Bench Mark                              |                                | Quarter<br>Other                                  | Corner                 |
| Your Description and                           | Observation of  | Monument Found (  | Be Specific ):                 |   |                        |
| Found Standard BLM                             | Cap 15ft ± ed   | ast of a north—sou  | th fence, on the               | north sl  | ope of a hill          |
| Description of Monum<br>Location of this Point |   | Monument or Acces   | sories Established             | d by You  | to Perpetuate the      |
| Set a #4 rebar north                           | , southwest, w  | est, and southeast  | of Monument                    |   |                        |
| Sketch showing Relati<br>Found or Set. Show S  |   |   |                                |   |                        |
| CAND MANUS                                     | 0720200600<br>NW COR S 12<br>T20S R7E SLM<br>STD. BLM CAP | S 87'25'31" W<br>SET #4 REI<br>S 42'00'51" W<br>SET #4 RE | 14.92' SE<br>BAR S<br>22.13' S | 13'48" W 1<br>T #4 REBAR<br>60'38'32"<br>SET #4 R | E 14.69'               |
| Certification: Firm name and/or St             | urveyor: Johan  | nsen & Tuttle Eng.  | Craig E.                       | Johansen  |                        |
| <u>-</u>                                       |   | le Dale, Utah 8451  |                                | Phone:  | (801) 381-2523         |
|  |   | e charge of the surveyi                                   |                                | this record                                       | d and that to the best |

Location Diagram:

Section: 12
Township: 20 S.

Range: 7 E.



Graig E Johnsonsen No. 14660

20 Na 98

No. 146602 CRAIG E. JOHANSEN