Date of field work:	7-1-03	County Reference No. 2117 100 400
	Section Corner Bench Mark	Quarter Corner Other
Your Description and (6"x 12" 5 AN \$570	Observation of Monument Found (NE 12" OUT OF GROUNE	Be Specific): WITH CC NOTCHES IN EAST SIDE
	ent, Reference Monument or Acces : SET 4 LEB AR AS SHO	sories Established by You to Perpetuate the WN .
Sketch showing Relativ Found or Set. Show S	ve Location of Monument Accessor Supporting and/or Contradictory Ev	ies and Two Reference Points Stating Whether idence where Applicable. Include North Arrow. N 1°01'09" W 18.89
ORIGINAL ROCK C.C.	N 85°15'04'W 10- 35.56 x	30° ROCK 30° ROCK 587°16'22" E 21.61 24 S1°33'22" E 25.92
Certification: Firm name and/or Su	urvevor: Johansen & Tuttle	Ena.
Address: 90 S.		84513 Phone: (435) 381-2523
This is to certify that of my knowledge the	I was in responsible charge of the survey information presented herein is true and c	ing work described in this record and that to the best orrect.
•		Linea de Landson
Location Diagram: Section: 18 Township: 215 Range: 17E	19	No. 146602 CRAIG E. JOHANSEN Date

Date of field work: _	7-22-03	County Reference No. 2117 1013 440
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other
Your Description and O SET 2' Alam	Observation of Monument Found (Be Specific): EYS CAA
Description of Monumer Location of this Point:	nt, Reference Monument or Access	sories Established by You to Perpetuate the
BUILT STONE	MOUND AROUND CAS.	
Sketch showing Relative Found or Set. Show Su	unporting and/or Contradictory Ev	ries and Two Reference Points Stating Whether vidence where Applicable. Include North Arrow. aッピ
1015 RITE 1015 RITE 2003	103853 N 588 58 31 W 0 - 108 0 118 10 29.43 10 29.43	36° 35' 10" E 31° 22.54
Certification:		
Firm name and/or Sur Address: 90 S. 1		Eng. 84513 Phone: (435) 381-2523
This is to certify that I of my knowledge the in	was in responsible charge of the surveying formation presented herein is true and c	ring work described in this record and that to the best correct.
Location Diagram: Section: 18 Township: U35 Range: 1718	Ø	No. 146602 S CRAIG E. JOHANSEN 8-20-03

Date of field work: 7-22-	- <u>03</u>	County Reference 1	No. <u>2117100500</u>
Type of Monument:	Section Corner Bench Mark	Quarter Other	Corner
Your Description and Observation SET 2" Alva Emery	on of Monument Found (B	e Specific): E ABOVE GROUND	
Description of Monument, Refe. Location of this Point: SET	rence Monument or Accesso 4 #9 Refac As	ries Established by You	to Perpetuate the
Sketch showing Relative Locating Found or Set. Show Supporting	on of Monument Accessories and/or Contradictory Evid	s and Two Reference Po ence where Applicable. It	nints Stating Whether nclude North Arrow.
E 0 5. 203 RITE 5/10 2003	589°36'11"W	ence where Applicable. II 12°00' 12" W 25.91	RIBAR
Certification:	l la como de Tuttle Eu	20	
Firm name and/or Surveyor: Address: 90 S. 100 E.	Johansen & Tuttle Er Castle Dale, Utah		(435) 381-2523
This is to certify that I was in r	esponsible charge of the surveying presented herein is true and corr	work described in this record	d and that to the best
Location Diagram: Section: 18 Townsnip: 215 Range: 17E		No. 146602 CRAIG E. JOHANSEN	January 1988

Date of field work: 7-7	22-03	County Reference No. 2117140400
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other
Your Description and Observ	ation of Monument Found (& ABOVE JROVN)	3e Specific):
Description of Monument, Re Location of this Point: 5E	eference Monument or Access	ories Established by You to Perpetuate the
Sketch showing Relative Loc Found or Set. Show Suppor	ting and/or Contradictory Evic	es and Two Reference Points Stating Whether dence where Applicable. Include North Arrow. N4°52'30"W 26.18 0 744 MARIENTE
A + 4 POST	0 580°11'12"W 29.01	ATA [] [] [] [] [] [] [] [] [] [] [] [] [] [
Certification:		
Firm name and/or Surveyor		·
Address: 90 S. 100		84513 Phone: (435) 381-2523
This is to certify that I was in of my knowledge the information	n responsible charge of the surveyin ion presented herein is true and co	g work described in this record and that to the best rect.
	4	erara Dansen
Location Diagram: Section: 10 Townsnip: 215 Range: 17E	8	No. 146602 CRAIG E. JOHANSEN S-20-03

Date of field work:	7-22-03	County Refer	ence No. <u>2117140440</u>
Type of Monument:	Section Corner Bench Mark	Qu Oti	arter Corner her <u>CENTER OF SE</u> C
Your Description and (SET 2' Em.	Observation of Monument Found (CO - 54 ENEY 5 Alson CAP	Be Specific): 3	
Location of this Point:	ent, Reference Monument or Access SET 4 #4 REBAR MOUND AROUND CAP	sories Established by	y You to Perpetuate the
Sketch showing Relativ Found or Set. Show S	ve Location of Monument Accessori Supporting and/or Contradictory Evi	idence where Applica	The medde for a farence
6 8 S 1215 RITE C)4 518 2003	88°54'30'W 588°54'30'W 5	- CAMININA 2-05-0 583° 44' 0 583° 27.9 10°13'53"W 25.72	O = # A REBAR Alo E O
Certification: Firm name and/or Sunddress: 90 S.		Eng. 84513 Pho	one: (435) 381-2523
This is to certify that	I was in responsible charge of the surveyi information presented herein is true and co	ng work described in thi orrect.	's record and that to the best
Location Diagram: Section: 19 Township: 0)5 Range: 17E		No. 146 CRAIC JOHAN	t E.

Date of field work: 7-22-03 County Reference No. 2117 200 400
Type of Monument: Section Corner Quarter Corner Bench Mark Other
Your Description and Observation of Monument Found (Be Specific): SET 2' EM. CO SURVEYS ALVM. CAP.
Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point: SET 4 # 4 REBAR AG SHOWN BUILT STONE MOVING ALOUND CAP.
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow. N2°04'47" 25.77 0: AR LEBAL N409°12'32" 28.72 180517 180517 180517 180517 180517 180517 180517 180517 180518 18051
Certification: Firm name and/or Surveyor:Johansen & Tuttle Eng. Address:90 S. 100 E. Castle Dale, Utah 84513Phone: _(435) 381-2523
This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct. Location Diagram: Section: Townsnip: 116 Range: 116 Date

Date of field work:	7-22-03		County Re	ference No. Z	117200440
Type of Monument:		ion Corner h Mark		Quarter Corne Other	r
Your Description and O SET 2" EM	Observation of Monum • CO 5 (JRNE)	nent Found (Be S NS PUVM	pecific): CHP		
Description of Monume Location of this Point:		4 REBAR AS			erpetuate the
Sketch showing Relative Found or Set. Show Standard Set. Show Standard Stan	Supporting and/or Co. N N 568'37'35"W 26.15	ntradictory Evidence	5 82°26'21" E	= #4 RB;	Stating Whether North Arrow. 22 570 NE 79 PU
Certification:					
Firm name and/or Su	ırveyor: Johanser	& Tuttle Eng.			
Address: 90 S.	100 E. Castle D	ale, Utah 845	513	Phone: <u>(435</u>) <u>381–2523</u>
This is to certify that of my knowledge the	I was in responsible charginformation presented here	ge of the surveying wor in is true and correct.	k described in	this record and	that to the best
Location Diagram: Section: 19 Township: 2.15 Range: 175		6	CRA	46602 P IG E. INSEN	<u></u>