

# EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 2-4-98 County Reference No. 0720540400  
 Type of Monument: \_\_\_\_\_ Section Corner X Quarter Corner  
 \_\_\_\_\_ Bench Mark \_\_\_\_\_ Other \_\_\_\_\_


Your Description and Observation of Monument Found ( Be Specific ):

Found Standard BLM Cap lying on the ground. Reset by single proportionate measure


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #4 rebar north, southwest, west, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0720540400  
 NORTH QTR. S20  
 T20S R7E SLM  
 STD. BLM CAP




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen  
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:  
 Section: 20  
 Township: 20 S.  
 Range: 7 E.



*Craig E. Johansen*  
 Craig E. Johansen

20 Nov. 1998  
 Date



# EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-19-98 County Reference No. 0720600400  
 Type of Monument: X Section Corner                      Quarter Corner  
                     Bench Mark                      Other                     


Your Description and Observation of Monument Found ( Be Specific ):

Found Standard GLO Cap along a east-west fence


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #4 rebar north, southwest, west, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0720600400  
 NW COR S20  
 T20S R7E SLM  
 STD. GLO CAP




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen  
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:  
 Section: 20  
 Township: 20 S.  
 Range: 7 E.



*Craig E. Johansen*  
 Craig E. Johansen

20 Nov. 1998  
 Date



# EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 1-19-98 County Reference No. 0720600340  
 Type of Monument: \_\_\_\_\_ Section Corner X Quarter Corner  
 \_\_\_\_\_ Bench Mark \_\_\_\_\_ Other \_\_\_\_\_


Your Description and Observation of Monument Found ( Be Specific ):

Found Standard GLO Cap


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #4 rebar north, southwest, west, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0720600340  
 WEST QTR. S 20  
 T20S R7E SLM  
 STD. GLO CAP




Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen  
 Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:  
 Section: 20  
 Township: 20 S.  
 Range: 7 E.



*Craig E. Johansen*  
 Craig E. Johansen

20 Nov. 1998  
 Date

