## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-1-97 County Reference No. 0819600400

Type of Manument: X Section Corner Quarter Corner

Type of Monument: X Section Corner Quarter Corner .

Bench Mark Other .


Your Description and Observation of Monument Found (Be Specific):

Found Standard KING Cap in a east-west-south fence corner

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set 2 #5 rebars South, and West of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 20
Township: 19 S.

Range: 8 E.

----20-----

Craig E. Johansen

/2/7/97 Date

### EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	4-1-97	•	County	Reference	No.'	0819540400
Type of Monument:		Section Corner Bench Mark	X	Quarter Other _	Corner	-
Your Description and	Observation of	Monument Found (	Be Specific ):			

Found Standard BLM Cap in a north—south fence line


Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:


Set two #5 rebars south, and north of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



0819540400 NORTH QTR S 20 T19S R8E SLM STD. BLM CAP





Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen


Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 20
Township: 19 S.

Range: 8 E.



Craig E. Johansen

/2/9/97 Pate

## EMERY COUNTY LAND SURVEY MONUMENT RECORD


Date of field work: $3-7-6$	<u>01</u>	County Reference No. 1908,2003.00
Type of Monument:	Section Corner	Quarter Corner
	Bench Mark	Other
Your Description and Observe	ation of Monument Found ( Be :	Specific ):
FOUND STD. KING CAP - 5	ET BY CHARLES V. KING	OF COON, KING AND KNOWLTON
IN 1975 RLS # 1929	(OLD NUMBER) FOR STEAR	45-ROGER INC. / UTAH POWER & LIGHT
		,
	ference Monument or Accessorie	s Established by You to Perpetuate the
Location of this Point:	ITHWEST, WEST, AND NORTH WEST OF	THE MONUMENT,
SELL LIGHT SOUTH SEL	, west, mass,	
	•	
		e where Applicable. Include North Arrow.
	ing and/or Contradictory Evidence	be where Applicable. Include North Arrow.
	ing and/or Contradictory Evidence	1
Found or Set. Show Supporti	N 53°56' 55″ω SET*4 Reburk	be where Applicable. Include North Arrow.
Found or Set. Show Supporti	ing and/or Contradictory Evidence	be where Applicable. Include North Arrow.
Found or Set. Show Supporti	N53°56'55" SET*4 Reburn	be where Applicable. Include North Arrow.
Found or Set. Show Supporti	N 53°56' 55″ω SET*4 Reburk	be where Applicable. Include North Arrow.
Found or Set. Show Supporti	N53°56'55"W SET*4 REDAR 40.01 X 5 X	be where Applicable. Include North Arrow.
Found or Set. Show Supporti	N53°56'55"W SET*4 REDAR 40.01 X 5 X	The where Applicable. Include North Arrow.  The property is a second of the property is a second of the property in the property in the property is a second of the property in the property in the property is a second of the property in the property in the property is a second of the property in the property in the property is a second of the property in the property in the property in the property is a second of the property in the property i
Found or Set. Show Supporting the Support the Supporting the Suppo	10 and/or Contradictory Evidence  N53°56'55" ω SET*4 Rebu?  40.01 × × ×  31.19 SERONR 0-  528°54'15" ω σ#4	The where Applicable. Include North Arrow.  Y-X-X  COUNTY ROAD  X  X  X  X  X  X  X  X  X  X  X  X  X
Found or Set. Show Supporting Res	10.01 SET*4 REDAR 0- 31.19 SES*54'15"W SET*4 REDAR 0- 46.01 SET*4 REDAR	The where Applicable. Include North Arrow.  Y-X-X  COUNTY ROAD  X  X  X  X  X  X  X  X  X  X  X  X  X
Found or Set. Show Supporting the Support the Supporting the Suppo	N53°56'55" SET*4 Rebu? 40.01 SET*4 Rebu? 31.19 SERBONR 0- 328°54'15" SET*4 Rebu? 46.01 SET*4 REONR Johansen & Tuttle Eng.	The where Applicable. Include North Arrow.  Y-X-X  COUNTY ROAD  X  X  X  X  X  X  X  X  X  X  X  X  X

Location Diagram:

Section: 20

Township: 195

Range: 8E




No. 146602 CRAIG E JOHANSEN

11-30 - 01

EMERY COUNTY LAND SURVEY MONUMENT RECORD					
Date of field work: 3-02-01		County Reference No. 1908 200 340			
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other			
Your Description and Observation of FOUND STANDARD BLM CAP AL					
Description of Monument, Reference Location of this Point:	Monument or Accessories	Established by You to Perpetuate the			
SET A #4 REBAR NORTH, NOR	THEAST, EAST & SOUT	HEAST OF MONUMENT			

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:

Johansen & Tuttle Eng. Firm name and/or Surveyor: (435)381 - 252384513 Castle Dale, Utah Phone: 90 S. 100 E.


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.


Location Diagram:

Section: 20

Township: 19 5

Range:





# UTAH LAND SURVEY MONUMENT RECORD

Clanty <u>BEMERY</u>		County Reference No. 2849 240 300
1. Date of Field Work: _	1-26-01	
2. Type of Monument: (Check one)	Section Corner Bench Mark	Quarter Corner Other
3. Your Description and O	bservation of Monument Fou	and (Be Specific):
FOUND STO BLM CAP AL	ong A North-South Fence	
	nt, Reference Monument or A west, and west, and 2 Nor	ccessories Established by You to Perpetuate the
5. Sketch showing Relative Found or Set. Show Supp	Location of Monument Accessoring and/or Contradictory	ssories and Two Reference Points Stating Whether Evidence where Applicable. Include North Arrow.
	584°40'56"W 15.53 SET 4 7 0	H1°32.65 H1°32.653
	635° 27.64	
6. Certification: Firm Name and/or Surveyor: Address: 90	OHANSEN TUTTLE  S 100 E CASTLEDALE	ENG Phone: 435)381-2523
This is to certify that I was in my knowledge the informatic	responsible charge of the surveying n presented herein is true and cor	g work described in this record and that to the best of
7. Location Diagram:  8. Section: 20  9. Township: 195  10. Range: 8E  T195 R8E  7 520  7 529	20	Signature No. 146602  Surveror's seal CRAIG E.  JOHANSEN  LECAL DE LA CONTROL DE LA CO
1975  Aug person:	12. Diagram Coordinate from Master Index for Townships:	Report one monument per form. Type or use permanent black ink. Fill in all items.