EMERY COUNTY LAND SURVEY MONUMENT RECORD

| Date of field work: | 1-16-98 | | County Refe | erence No. <u>072</u> 0 | 0300400 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|--------------------------------------------------------------|-----------------------------------------------------------|--------------------------------------------------------------------------------|-----------------------|
| Type of Monument: | XS | Section Corner | Q | uarter Corner | |
| | | lench Mark | C | ther | |
| Your Description and | Observation of Mo | nument Found (Be . | Specific): | | |
| Found Standard BLM (| Cap 3 ft ± west | of a north—south—e | ast—west fence | e corner | |
| Description of Monume Location of this Point: | ent, Reference Mor | nument or Accessorie | s Established l | by You to Perpeti | uate the |
| Set a #4 rebar north, | south, west, an | d east of Monument | | | |
| Sketch showing Relativ Found or Set. Show S | e Location of Mor upporting and/or | nument Accessories a Contradictory Evidenc | nd Two Refere e where Applic | nce Points Statin able. Include Nor | g Whethe th Arrow. |
| CADASTRAL SUPERIOR TO THE SUPERIOR SUPE | 0720300400 NW COR S 23 T20S R7E SLM STD. BLM CAP | SET #4 REBAR S 82'18'27'' W 25. S 08'18'36'' SET #4 | 67' E 25.57' | SET #4 REBAR 17'41'23" E 26.31' S 87'58'21" E 19.50' SET #4 REBAR | |
| Certification: | | | I | | |
| Firm name and/or Sui Address: 90 South | *************************************** | | Craig E. Job | | 4 0507 |
| This is to certify that I | 100 East, Castle was in responsible character formation presented h | narge of the surveying workerein is true and correct. | | hone: (801) 38 is record and that to | |
| Location Diagram: Section: 23 Township: 20 S. Range: 7 E. | 23 | Zo n | Craig 7. January 1. January 1. January 1. January 1. Date | Tonsen No. 146602 CRAIG E. JOHANSEN | |

EMERY COUNTY LAND SURVEY MONUMENT RECORD

| | | · · | <u></u> | + + , | |
|-------------------------------------------------|------------------------|--------------------------------------------------------------|-------------------|--------------------|-------------------------------------------|
| Date of field work: | 1-16-98 | | County Refe | rence No. | 0720240400 |
| Type of Monument: | | Section Corner | | uarter Corn | ier |
| | | Bench Mark | 0 | ther | |
| Your Description and | Observation of | Monument Found (Be | Specific): | | |
| Found Standard ECS | Cap along a ec | ast—west fence | | | |
| Description of Monume Location of this Point | | Monument or Accessor | ies Established t | by You to 1 | Perpetuate the |
| Set two #4 rebars we | st, and east o | of Monument | | | |
| | | Monument Accessories for Contradictory Eviden | | | |
| Certification: | | 14 2 E. | | WAR SE | b. |
| Firm name and/or St | ırveyor: <u>Joha</u> ı | nsen & Tuttle Eng. | Craig E. Jol | hansen | |
| Address: 90 South | 100 East, Cas | tle Dale, Utah 84513 | P | Phone: <u>(8</u> 6 | 01) 381–2523 |
| | | ole charge of the surveying vited herein is true and correct | | is record and | that to the best |
| | | عمد | | Do | |
| | | <i>(a.</i> | aig E Jo | horsen | W. S. |
| Location Diagram: | 1 | | Jordiy k. 00 | 1737 | 146600 12/1 |
| Section: 23 | 1 | | Š. | [4] No. | 146602 \\$\\$ |

20 S. Township:

Range:

No. 146602 CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD

| Date of field work: | 1-21-98 | | County R | eference No. <u>0720300340</u> | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|----------------------------------------------|--------------------|-----------------------------------------------------------------|--|--|
| Type of Monument: | *************************************** | Section Corner | X | Quarter Corner | | |
| | | Bench Mark | | Other | | |
| Your Description and | Observation of | Monument Found (| Be Specific): | | | |
| Found Standard BLM | WC Cap along | the south edge of a | a cultivated firld | | | |
| Description of Monum Location of this Point | | Monument or Access | sories Established | d by You to Perpetuate the | | |
| Set two #4 rebars so | uthwest and so | outheast of Monumer | nt , | | | |
| Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow. | | | | | | |
| WC 522 523 E | 0720300340 WEST QTR. S23 T2OS R7E SLM STD. BLM WC CAP | S 36'43'25'' W 51.73 SET #4 REBAR | - WIT | 21'02" E 19.79' INESS CORNER S 46'53'41" E 54.75' SET #4 REBAR | | |
| Certification: | | | ω | | | |
| Firm name and/or Su Address: 90 South | | nsen & Tuttle Eng. tle Dale, Utah 8451. | Craig E | Johansen Phone: (801) 381-2523 | | |
| This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct. | | | | | | |
| Location Diagram: Section: 23 Township: 20 S. Range: 7 E. | •23 | 3 Qu | Craig E | Johonsep No. 146602 CRAIG E. JOHANSEN | | |