## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	1-21-98		County	Reference	No. <u>0720300300</u>
Type of Monument:	X	Section Corner		Quarter	Corner
		Bench Mark	· ·	Other _	***************************************
Your Description and	Observation of	Monument Found (	Be Specific ):		
Found Standard BLM	Cap at a north-	-southeast fence co	orner		
Description of Monum Location of this Point	ent, Reference M :	Monument or Access	sories Establish	ed by You	to Perpetuate the
Set a #4 rebar north	. southwest. w	est. and southeast	of Monument		
"	, ===	,	·		
Sketch showing Relative Found or Set. Show S	ve Location of M Supporting and/o	Monument Accessorie or Contradictory Evic	es and Two Re dence where Ap	ference Po oplicable. I	oints Stating Whether Include North Arrow.
S22 S23	0720300300 NW COR S 26 T20S R7E SLM STD. BLM CAP	S 74°37′13″ W 23. SET #4 REBAR S 23°41′49″ W 3 SET #4 REBAI	.38' \$	'40'39" W 1: SET #4 REBA 20'30'33" E SET #4 REE	25.69'
Certification:					
Firm name and/or Su	ırveyor: Johan:	sen & Tuttle Ena.	Craia E.	Johansen	
	' <u>'</u>	e Dale, Utah 84513		Phone:	(801) 381-2523
		charge of the surveying d herein is true and cor		n this recor	d and that to the best
Location Diagram: Section: 26 Township: 20 S. Range: 7 E.	26-	2	Craig E,  Craig E,  Date		No. 146602 CRAIG E. JOHANSEN

## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	1-14-98		County R	eference No.	0720240300
Type of Monument:		Section Corner	X	Quarter Cor	ner
		Bench Mark	· ·	Other	er e
Your Description and	Observation of	Monument Found (	Be Specific ):		
Found Standard BLM	Cap in a mour	nd of stone			
Description of Monume Location of this Point		Monument or Access	ories Established	d by You to	Perpetuate the
Set a #4 rebar north	, southwest, v	vest, and southeast	of Monument		
Sketch showing Relativ					
Found or Set. Show S	Supporting and/	or Contradictory Evic	lence where App	olicable. Inclu	de North Arrow.
CTRAI		,			
	0720240300	SET #4 REBAR		" W 20.87" 4 REBAR	
© 1/4 ——— E	NORTH QTR. S26 [20S R7E SLM STD. BLM CAP	S 75'23'08" W 14.	90' O S 6	64*13'42'' E 22.6	51'
1962		S 12°22'19" W SET #4 REB	21.38'	SET #4 REBAR	
LAND MA					~
Certification:					
Firm name and/or Su	ırveyor:Johai	nsen & Tuttle Eng.	Craig E.	Johansen	
Address: 90 South	100 East, Cas	tle Dale, Utah 84513		Phone: <u>(</u> 8	301) 381-2523
		le charge of the surveying ed herein is true and cor		this record an	d that to the best
		7			
Location Diagram:	•		Craig/E.	Johansen	
Section: 26			1 //	No PEL	. 146602
Township: 20 S.	2	<u></u>		911	PATG F

Range: <u>7 E.</u>