EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 2-2-98 County Reference No. 0720440300

Type of Monument: Section Corner X Quarter Corner
Bench Mark X Other WITNESS CORNER


Your Description and Observation of Monument Found (Be Specific):

Found Standard BLM Witness Cap on the south edge of a field inline with a north—south fence to the south

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Set a #4 rebar southwest, south, and two southeast of the Witness Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:

Firm name and/or Surveyor: <u>Johansen & Tuttle Eng.</u> Craig E. Johansen


Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (801) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 28
Township: 20 S.

Range: 7 E.



Craig E. Johansen

Zo Nov. 1998

No. 146602 CRAIG E. JOHANSEN

LAND ST

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	1-23-98		County	Reference	No. <u>0720500300</u>
Type of Monument:	X	Section Corner Bench Mark		Quarter Other	Corner
Your Description and	Observation of	Monument Found (Be Specific):		
Found Standard BLM	Cap				
Description of Monume Location of this Point		Monument or Access	sories Establish	ed by You	to Perpetuate the
Set a #4 rebar north	, southwest, w	est, and southeast	of Monument		
Sketch showing Relation Found or Set. Show S					
S20 S21	0720500300 NW COR S 28 T2OS R7E SLM STD. BLM CAP	SET #4 REB/ S 85'27'26" W S 34'15'05" W SET #4 REB	10.98	5'47" W 14.1 T #4 REBAR 38'36'05" E - SET #4 REB/	16.88'
Certification:					
Firm name and/or St Address: 90 South	·	isen & Tuttle Eng. de Dale, Utah 84510		. Johansen Phone:	(801) 381-2523
This is to certify that	I was in responsibl	e charge of the surveying the condition of the condition	g work described	•	
	_	<u>∕</u>		0 (1	
Location Diagram:	•		Craig E	/ Johanser	ausur

Section: 28
Township: 20 S.

7 E.

Range: __

20 Nov. 1998

No. 146602 & CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD


Date of field work:	1-20-98	County	Reference	No	0720500240
Type of Monument:	Section Cor	******	Quarter Other _	Corner	
Your Description and	Observation of Monument Fo	ound (Be Specific):			
Found Standard BLM	Cap ontop of a hill in a old	d gravel pit			

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:

Raised a mound of stone around the Monument

Set a #4 rebar north, southwest, west, and southeast of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



Certification:

Firm name and/or Surveyor: <u>Johansen & Tuttle Eng.</u> <u>Craig E. Johansen</u>


Address: <u>90 South 100 East, Castle Dale, Utah 84513</u> Phone: (801) 381-2523

This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 28
Township: 20 S.

Range: 7 E.



Craig E. Johansen

20 Nov. 1998

No. 146602 CRAIG E. JOHANSEN