
EMERY COUNTY LAND SURVEY MONUMENT RECORD							
Date of field work:	3-26-97	•	County	Reference	No.	0819400700	
Type of Monument:	X	Section Corner Bench Mark		_ Quarter _ Other _			
Your Description and	Observation of	Monument Found (Be Specific):				
Found Standard ECS	Cap,in a East,	West fence					
Description of Monum Location of this Point		Monument or Acces	sories Establisl	ned by You	ı to 1	Perpetuate the	
Set a #5 rebar South	nwest, and Sou	th, and two #5 rebo	ars Southeast	of Monume	ent		
Sketch showing Relati Found or Set. Show							
		0819400	700				



Certification:

Firm name and/or Surveyor: Johansen & Tuttle Eng. Craig E. Johansen

Address: 90 South 100 East, Castle Dale, Utah 84513 Phone: (435) 381-2523


This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:

Section: 3

Township: __19 S.

Range: 8 E.



Craig E. Johansen

/2/9/97 Date

EMERY COUNTY LAND SURVEY MONUMENT RECORD

					,
Date of field work:	3-26-97	·	County Re		o. <u>0819400640</u>
Type of Monument:		Section Corner Bench Mark	X	Quarter C Other	orner ·
Your Description and	Observation of	Monument Found (Be Specific):		
Found Standard ECS	Cap, in a North	, East ,and West	fence corner		
Description of Monume Location of this Point		Monument or Acces	sories Established	d by You t	o Perpetuate the
Set #5 rebar, Souther	ast, and Southw	est of Monument			
Sketch showing Relative Found or Set. Show S	ve Location of Supporting and/	Monument Accessor or Contradictory Ev	ies and Two Refe idence where App	erence Poir olicable. Inc	nts Stating Wheth clude North Arrow
COUNTY SURVEYS 1/4 4 + 3 1/5 RBE SLM 1884	08194006 WEST QTR T19S R8E ECS CAP S 82°23' SET SET 60°46'56' W 80° SET#5 R6	S 3 SLM 07' W , 32.24 O #5 REBAR	SET #5 REBAR N 01'39'37" W , 2	21.17	
Certification:					
Firm name and/or St Address: 90 South		nsen & Tuttle Eng. tle Dale, Utah 8451	Craig E.		(435) 381-2523
This is to certify that	I was in responsibl	le charge of the surveyi ed herein is true and c	ing work described in	this record	and that to the best
Location Diagram: Section: 3 Township: 19 S. Range: 8 F	•3		Craig E.	Johansen	<u>uru</u>


EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date	of field work:	3-25-97	•	County	Reference	No	0819340700
Туре	of Monument:		Section Corner Bench Mark	Х	Quarter Other	Corner	
Your Description and Observation of Monument Found (Be Specific):							
Set	a 8" x 3/8" spik	ke in county roo	ad using Standard E0	CS RM Caps			

Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:


Set a #5 rebar Southwest, and Northwest of Monument

Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.



This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.

Location Diagram:
Section: 3
Township: 19 S.
Range: 8 E.



araig E. Johansen

/2/9/97