## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	11-1-04		County Re	eference No	. <u>2206 300 100</u>
Type of Monument:		Section Corner Bench Mark		Quarter Co	orner
Your Description and 1979 BLM CAP	Observation of 2" ABIVE G	Monument Found ( RCいいり IN AS	Be Specific ): TONE 140 UND		
Description of Monum Location of this Point				by You to	Perpetuate the
Sketch showing Relating Found or Set. Show	ve Location of Supporting and/ N	Monument Accessor or Contradictory Ev	ies and Two Refe idence where App	rence Poin licable. Inc	ts Stating Whether lude North Arrow.
7225 RGE 532   533 55   54 T 235 1978		Bot	70:49 WASH N 51°08'51"W 14:48	* A SHE	N 75°09'36" E 13.99
Certification:  Firm name and/or S  Address: 90 S.		ansen & Tuttle Itle Dale, Utah		A REBAR Phone: 4	546°28'41"E 18.34 35) 381-2523
This is to certify that of my knowledge the	I was in responsib information present	ole charge of the survey ted herein is true and c	ing work described in correct.	this record	and that to the best
Location Diagram: Section: 32 Township: 225 Range: 6E	3	L	No. 14 CRAIG JOHAN 17-24-	usen / /	

## EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 11-1-04 County Reference No. 2206 300	
Type of Monument: Section Corner Quarter Corner	<u> </u>
Type of Monument: Section Corner Quarter Corner  Bench Mark Other	
Your Description and Observation of Monument Found (Be Specific):  ALUM. OP @ GROUND LEVEL IN A SMAIL MOUND OF STONE	
Description of Management Defendance Management on Association Established by You to Described to	
Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point: SET A #4 REBAR AS SHOWN BELLOW	ıę
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whet Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arro	ther w.
N 9°24'11"E	
10.81	
BANK	
14 cor. N MANNE SMALL	
32/33 \$ 569°42'01"W TO 000 000 0000 TO	
722 5 RIVES 12.30 13.30	
LEDEE	-
50°11′38′ω 12.42	
Certification:	
Firm name and/or Surveyor: Johansen & Tuttle Eng.	
Address: 90 S. 100 E. Castle Dale, Utah 84513 Phone: (435) 381-25	23
This is to certify that I was in responsible charge of the surveying work described in this record and that to the be of my knowledge the information presented herein is true and correct.	st
JUNIO 8 LAND 8 L	
Coffee to Johnson	
Location Diagram:	
Section: 32 CRAIG E. JOHANSEN	
Township: 225  Range: 6 = 10HANSEN  (1-24 04)	