EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 10-20-04	<u>-</u>	County Reference No. 2106440100
Type of Monument:	Section Corner Bench Mark	Quarter Corner Other
Your Description and Observation of 1978 BLM CAP G'ABOVE GRE ON THE SOUTH SIDE OF CA	OUND IN FENCELINE	DECIFIC): WITH A MOUND OF STONE
Description of Monument, Reference Location of this Point: SET 4	ce Monument or Accessories *4 REBAR AS SHOWN	Established by You to Perpetuate the BELOW
Sketch showing Relative Location Found or Set. Show Supporting an	of Monument Accessories an nd/or Contradictory Evidence	d Two Reference Points Stating Whether where Applicable. Include North Arrow.
V T 215 R 6 E 7 N 77° 31' 52 16.50 14 \$ 34		
Certification:		
	ohansen & Tuttle Eng. Castle Dale, Utah 84	513 Phone: (435) 381-2523
This is to certify that I was in respondent of my knowledge the information pre-	onsible charge of the surveying wor esented herein is true and correct.	k described in this record and that to the best
•	Cos	aven aum
Location Diagram: Section: 34 Township: 2\5 Range: 6E	-34	No. 146602 S CRAIG E. JOHANSEN

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	11-1-04		County R	Reference No. 2106 500 140
Type of Monument:	 .	ction Corner nch Mark		Quarter Corner Other
Your Description and Ol 1979 BLM CAJA 4	bservation of Mon	ument Found (Be	Specific):	PLANTED ON NORTH SID
	,			
Description of Monumen Location of this Point:	t, Reference Mond	ument or Accessor	ries Establishe wn Belou	d by You to Perpetuate the
Sketch showing Relative Found or Set. Show Su	Location of Mon	ument Accessories Contradictory Evide	and Two Rei ince where Ap	ference Points Stating Whether policable. Include North Arrow.
ST215RGE	H	1 N 22° 28' 41" (Ų	CECEDAR POST CERNER
534 535 1979 COTO DIM N E	- X-X- REAN - X-X-	O ONA WORK ST	· X 76°44'34`E 13.09	
Certification:	17.43	5 21°46'48"E 17.86		
Firm name and/or Sur Address: <u>90 S. 1</u> 0		en & Tuttle En Dale, Utah 8	g. 84513	Phone: (435) 381-2523
This is to certify that I of my knowledge the int				in this record and that to the best
		É	card se	AND STREET
Location Diagram: Section: 34 Township: 215	34		JOH	146602 AAIG E. HANSEN
Range: <u>6E</u>		2		-23-04 KONUTAN

EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	11-1-04		County R	Reference No. 2106 500 140
Type of Monument:	 .	ction Corner nch Mark		Quarter Corner Other
Your Description and Ol 1979 BLM CAJA 4	bservation of Mon	ument Found (Be	Specific):	PLANTED ON NORTH SID
	,			
Description of Monumen Location of this Point:	t, Reference Mond	ument or Accessor	ries Establishe wn Belou	d by You to Perpetuate the
Sketch showing Relative Found or Set. Show Su	Location of Mon	ument Accessories Contradictory Evide	and Two Rei ince where Ap	ference Points Stating Whether policable. Include North Arrow.
ST215RGE	H	1 N 22° 28' 41" (Ų	CECEDAR POST CERNER
534 535 1979 COTO DIM N E	- X-X- REAN - X-X-	O ONA WORK ST	· X 76°44'34`E 13.09	
Certification:	17.43	5 21°46'48"E 17.86		
Firm name and/or Sur Address: <u>90 S. 1</u> 0		en & Tuttle En Dale, Utah 8	g. 84513	Phone: (435) 381-2523
This is to certify that I of my knowledge the int				in this record and that to the best
		É	card se	AND STREET
Location Diagram: Section: 34 Township: 215	34		JOH	146602 AAIG E. HANSEN
Range: <u>6E</u>		2		-23-04 KONUTAN