EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work: 4-07-97 Type of Monument: X	·	Reference No. <u>0919700700</u> Quarter Corner Other
Your Description and Observation of	Monument Found (Be Specific):	
Found Standard BLM Cap, 2.0' North	of a mound of stone.	
Description of Monument, Reference Monument or Accessories Established by You to Perpetuate the Location of this Point:		
Set #5 rebar North, Southwest, Southeast, and West of Monument		
Sketch showing Relative Location of Monument Accessories and Two Reference Points Stating Whether Found or Set. Show Supporting and/or Contradictory Evidence where Applicable. Include North Arrow.		
T18S R8E R9E S36 S31 S1 S6 W COR S 6 T19S R9E SID. BLM CAP		#5 REBAR 10.05 1.30" E.
Certification: .		
Firm name and/or Surveyor: <u>Johan</u> Address: <u>90 South 100 East, Cast</u>		Johansen Phone: (435) 381-2523
This is to certify that I was in responsible charge of the surveying work described in this record and that to the best of my knowledge the information presented herein is true and correct.		
Location Diagram: Section: 6 Township: 19 S. Range: 9 E.	Zo Nov. Date	Johansen No. 146602 CRAIG E JOHANSEN