EMERY COUNTY LAND SURVEY MONUMENT RECORD

Date of field work:	4-7-97	•	Coun	ty Reference	No. <u>0819600540</u>
Type of Monument:		Section Corn	ner X		Corner
	- Marine	Bench Mark		Other .	
Your Description and	Observation of	Monument Fou	und (Be Specific):	
Found Standard BLM	Cap in a north	, south, east,	and west fence (corner	
Description of Monume Location of this Point	ent, Reference :	Monument or	Accessories Estab	lished by Yo	u to Perpetuate the
Set 2 #5 rebars east	, and North of	Monument			
Sketch showing Relative Found or Set. Show S	ve Location of Supporting and,	Monument Acc or Contradicto	cessories and Two ory Evidence when	Reference F e Applicable.	Points Stating Whethe Include North Arrow.
S. T19S R8E 1/4 BD S7 + S8 1975 CAND MATTER OF LAND	0819600540 WEST QTR S8 T19S R8E SLM STD. BLM CAP	SET #5 REE N 15'14'51"	BAR 0 77 0 S	REBAR " E , 18.57 ET #5 REBAR 7'28'27" E , 24.	05
Certification:					
Firm name and/or S				g E. Johanse	
Address: 90 South	100 East, Cas	stle Dale, Utah	84513	Phone	: <u>(435) 381–2523</u>
This is to certify that of my knowledge the	I was in responsii information presen	ble charge of the ted herein is true	surveying work descreat.	ibed in this rec	ord and that to the best
				20	0
	-		Texaig	ia E Johansi	en
Location Diagram:]		7°		J.,
Section: 8 Township: 19 S.		R			
Range: 8 E.) 	12/2	10-	
	i.		104/7 Dat	17/	

EMERY COUNTY LAND SURVEY MONUMENT RECORD

£ 1716=1				
Date of field work:	3-28-97	•	County Reference	No. <u>0819600600</u>
Type of Monument:	X	Section Corner _		Corner
		Bench Mark	Other .	
Your Description and	Observation of	Monument Found (Be	: Specific):	
Found Standard BLM	Cap in the eas	t right of way fence o	of county road	
Description of Monum Location of this Point	ent, Reference t:	Monument or Accessor	ries Established by You	ı to Perpetuate the
Set a #5 rebar South	hwest, South, N	orth, and Northwest o	f Monument	
Sketch showing Relative Found or Set. Show OF TIPS REE S6 S5 T1975 1975 LAND WANTED TABLE TO THE TIPS REE LAND LAND LAND SECTION 1975 LAND LAND SECTION 1975 LAND LAND LAND SECTION 1975 LAND LAND	ive Location of Supporting and/ 0819600600 NW COR S 8	Monument Accessories or Contradictory Evide SET #5 REBAR N 63'40'10" W . 31.56 SET #5 REBAR S 58'50'35" W , 31.69	s and Two Reference Fence where Applicable. SET #5 REBAR N 03'23'30" W , SET #5 REBAR S 02'23'41" W ,	16.69
	T19S R8E SLM			
Certification:		0. Tulkla Coo	Craig E. Johanse	an
Firm name and/or S Address: 90 South		nsen & Tuttle Eng. stle Dale, Utah 84513	Phone	
This is to certify tha	t I was in responsi		work described in this recrect.	ord and that to the best
		7	/ . ~) <i>!</i>	0
	•		Claig F. Johans	aulu- en
Location Diagram: Section: 8			10	
Township: 19 S.	{	3		
Range: 8 E.			12/9/97	
			Date	